STATE OF OREGON

WELL	ID#L	L70755

WATER SUPPLY WELL REPORT

(as required by ORS 537.765)
Instructions for completing this report are on the last page of this form

(START CARD) # 168523

(1) OWNER:	Well Number	·	(9) LOCATION OF WELL by legal description: County Waso Latitude 40.508 Longitude 21.4	443
Name W. B. Reeves Address 1250 State Rd.	State OP	Zip 97040	Township 2N N or S. Range 12E E or W. of WM. Section 7 NE 1/4 NE 1/4	-1-
City Mosier	out OK	2º 3/040	Tax lot Block Subdivision Street Address of Well (or nearest address) 1250 State Rd.,	
(2) TYPE OF WORK: New Well Deepening	X Alteration (repair/recondit	ion) Abandonment	Mosier,OR	
	Alteration (repair/recondit	OI) Abandonment	(10) STATIC WATER LEVEL:	_
(3) DRILL METHOD:		F1 -	ft. below land surface. Date	_
X Rotary Air ☐ Rotary Mu ☐ Other	ıd Cable	Auger	Artesian pressurelb. per square inch. Date	_
(4) PROPOSED USE:			(11) WATER BEARING ZONES:	
Domestic Communi	tv Industrial	X Irrigation	Depth at which water was first found	
Thermal Injection	Livestock	Other	From To Estimated Flow Rate SWL	
(5) BORE HOLE CONSTR	RUCTION:			
Special Construction approval		ompleted Well ft.		
Explosives used Yes X No		mount		_
HOLE	SEAL Material From T	Amount sacks or pounds	(12) WELL LOG:	
Diameter From To 10" 283 490	materiai Proiii i	o sacks of poulids	Ground elevation	
			Material From To SWI	
			Cemented Well to Stabilize Caverens, 2" Steel pipe became stuck and cement set up before 2" pipe	-
			could be removed Temporarily Abandon until	\dashv
			property owner decides what course of action he	\exists
How was seal placed: Method	A B C D	∐ E	would like to take.	\dashv
Backfill placed from ft. to	o ft. Material		More info. on this well.	-
Gravel placed from ft. to	o ft. Size of grav	el	We reamed the hole to 10" to 490 ft., Plugged the	4
(6) CASING/LINER:			hole at 455 pumped in 6 yds, sand cement mix 8 bags to the yard. this filled the hole back to 294	\dashv
Diameter From T	o Gauge Steel Plas	tic Welded Threaded	ft., We started pulling grout pipe. Pulled back	
Casing:			to 426 ft. Pipe became stuck in the hole. We	
			attempted to overream the pipe and cut it off at	
			305ft. So we have 121 ft. of steel 2" pipe cemented in the hole, it is also full of cement.	\dashv
Liner:				
Final location of shoe(s)			DECEN/ED	
	SENG.		RECEIVED	
(7) PERFORATIONS/SCF			NAV 0 0 0001	_
Perforations Meth		al	NOV 2 3 2004	
Slot	Tele/pipe		WATER RESOURCES DEPT	
From To size Num	nber Diameter size	Casing Liner	SALEM, OREGON	\dashv
			Date started 07/28/2004 Completed 09/25/2004	_
		-	(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment	į.
			of this well is in compliance with Oregon water supply well construction standards.	
(8) WELL TESTS: Minim		_	Materials used and information reported above are true to my best knowledge and	
Pump Bailer	Air	Flowing Artesian	belief. WWC Number	
Yield gal/min Drawdowr	n Drill stem at	Time	Signed Date	_
			(bonded) Water Well Constructor Certification:	
			I accept responsibility for the construction, alteration, or abandonment work	
			performed on this well during the construction dates reported above. All work performed during this tipper in compliance with Oregon water supply well	
Temperature of Water Depth Artesian Flow found Was a water analysis done? Yes By whom			construction standards. This report is true to the best of my knowledge and belief.	
Did any strata contain water not s	uitable for intended use?	Too little	WWC Number 790	
Salty Muddy Odor	Colored Other		Signed Date 10/16/2004	
Depth of strata:			Charles Austin	

WASC 51295

STATE OF OREGON WATER SUPPLY WELL REPORT

(as required by ORS 537.765) instructions for completing this report are on the last page of this form

(START CARD) # 168523

1) OWNER: Well Number:	(9) LOCATION OF WELL by legal description: County Waso Latitude 40.508 Longitude 21.413
Name W. B. Reeves	Township 2N N or S. Range 12E E or W. of WM.
Address 1250 State Rd. City Mosier State OR Zip 97040	Section 7 SE 1/4 NE 1/4 Tax lot 100 Lot Block Subdivision
2) TYPE OF WORK:	Street Address of Well (or nearest address) 1250 State Rd.,
New Well Deepening X Alteration (repair/recondition) Abandonment	Mosier,OR
3) DRILL METHOD:	(10) STATIC WATER LEVEL: ft. below land surface. Date
X Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger	Artesian pressure lb. per square inch. Date
Other	(11) WATER BEARING ZONES:
(4) PROPOSED USE:	Depth at which water was first found
□ Domestic □ Community □ Industrial X Irrigation □ Thermal □ Injection □ Livestock □ Other	From To Estimated Flow Rate SWL
Themas Jayouton	
(5) BORE HOLE CONSTRUCTION: Special Construction approval ☐ Yes ☒ No Depth of Completed Wellft.	
Explosives used Yes X No TypeAmount	
HOLE SEAL Amount Diameter From To Material From To sacks or pounds	(12) WELL LOG:
Diameter Prom 10 material 110m.	Ground elevation
	Material From To SWL Cemented Well to Stabilize Caverens, 2" Steel pipe
	became stuck and cement set up before 2" pipe
	could be removed Temporarily Abandon until
	property owner decides what course of action he
How was seal placed: Method ☐A ☐B ☐C ☐D ☐E	would like to take.
Other Backfill placed from ft. to ft. Material	
Gravel placed from ft. to ft. Size of gravel	
(6) CASING/LINER:	
Casing:	
Final location of shoe(s)	007 21 2004
(7) PERFORATIONS/SCREENS:	UUI WII
Perforations Method Screens Type Material	WATER RESOURCES DEPT SALEM, OREGON
Slot Tele/pipe	30,000
From To size Number Diameter size Casing Liner	
	Date started 07/28/2004 Completed 09/25/2004
	(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment
	of this well is in compliance with Oregon water supply well construction standards.
(8) WELL TESTS: Minimum testing time is 1 hour	Materials used and information reported above are true to my best knowledge and
Pump Bailer Air Flowing Artesian	belief.
Yield gal/min Drawdown Drill stem at Time	Signed Date
	(bonded) Water Well Constructor Certification:
	l accept responsibility for the construction, alteration, or abandonment work
	performed on this well during the construction dates reported above. All work
Temperature of Water Depth Artesian Flow found	performed during this time is in compliance with Oregon water supply well
Was a water analysis done? Yes By whom	construction standards. This report is true to the best of my knowledge and belief.
Did any strata contain water not suitable for intended use?	Signed To Late 10/16/2004
Salty Muddy Odor Colored Other Depth of strata:	Charles Austin
ORIGINAL - WATER RESOURCES DEPARTMENT FIRST COPY - COPY	
UKIGINAL - WATER RESOURCES DEPARTIMENT FIRST COPT - COP	1011001011