Jamh WELL I.D. # L02185

APR - 2-1907

REPORT

STATE OF OREGON

WATER SUPPLY WELL REPORT (as required by OR\$ 537.765) Instructions for completing this report are on the last page of this form.	WATER RESOURCESTURED)# 95175
(1) OWNER: Well Number 2	SALEM, OREGON
Name Parrett Mountain Water Improvement District	(9) LOCATION OF WELL by legal description: t County Yamhill Latitude Longitude
Address C/O 11880 Lauren Lane	20 Edigitude
City Newberg State OR. Zip 97132	23 MI To Range To Boll W. W.M.
(2) TYPE OF WORK	
New Well Deepening Alteration (repair/recondition) Abandonment	Tax Lot 1000 Lot Block Subdivision PME Street Address of Well (or nearest address) 33030 Old Parrett Min. Rd
(3) DRILL METHOD:	Newberg, OR.
X Rotary Air Rotary Mud Cable Auger	(10) STATIC WATER LEVEL:
Other	205 ft. below land surface. Date 3/5/97
(4) PROPOSED USE:	Artesian pressurelb. per square inch. Date
Domestic Community Industrial Irrigation	(11) WATER BEARING ZONES:
Thermal Injection Livestock Other	
(5) BORE HOLE CONSTRUCTION:	Depth at which water was first found NA - No new drilling
Special Construction approval Yes No Depth of Completed Well 285 ft.	
Explosives used Yes No Type Amount	From To Estimated Flow Rate SWI
HOLE SEAL	
Diameter From To Material From To Sacks or pounds	
Not Changed	NA - No New Drilling
See (12) for work done	
	·
	(12) WELL LOG:
How was seal placed: Method A B C D E	Ground Elevationapprox 700'
Other	
Backfill placed from ft. to ft. Material	Material From To SWL
Gravel placed from ft. to ft. Size of gravel	No new drilling
(6) CASING/LINER: existing	Existing well is Yamh 167 SC# 18720.
Diameter From To Gauge Steel Plastic Welded Threaded	Well Exhibited intermittent quality problems
Casing: 6 +2 247 .250 X	and had inconsistently been heard having
	cascading water.
	We backfilled, perfed (3X) & pressure grouted
	(5X) through new perforations in an attempt to
iner:	seal the annulus below the evicting surface
	seal. Only final grout placement pressured up
Final location of shoe(s)	OWRD inspector, Richard Edwards, logged hole
7) PERFORATIONS/SCREENS(only new perforations are,	after last grout placement. Temp log indicates
Perforations Method air rotary listed)	grout is up to at least 130' and maybe much
Screens Type Material Slot Tele/pipe	higher. Total of 76 sacks cement grout used.
From To size Number Diameter size Casing Liner	After temp log, we drilled out grout plugs
75 198 2XI 500 = ================================	and backfill.
	Subsequent quality tests and stethoscopic
	minitoring have revealed no more problems.
WELL TECTS. Minimum	1/00/05
) WELL TESTS: Minimum testing time is 1 hour	Date started 1/29/97 Completed 3/5/97
Flowing	(unbonded) Water Well Constructor Certification:
	I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards.
Yield gal/min Drawdown Drill stem at Time	Materials used and information reports above are true to the best of my knowledge
	and belier.
ump 80* 22.8 15.8 hr ump 80* 43.2 36.7 hr	WWC Number 1367
445090	Date 3/26/97
	(bonded) Water Well Constructor Certification:
Vas a water analysis done? Yes By whom	accept responsibility for the construction, alteration, or abandonment work
	Deficience on Milk well during the construction dates reported above. All work
old any strata contain water not suitable for intended use? Too little	
Salty Muddy Odor Colored Other	performed during this time is in compliance with Oregon water supply well construction standards. This people is true to the best of my knowledge and belief.
Salty Muddy Odor Colored Otherepth of strata:	Www Number 649
oid any strata contain water not suitable for intended use?	Www Number 649