RECEIVED

OCT 2 0 1999

STATE OF OREGON WATER SUPPLY WELL REPORESOURCES DERVEL
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this (9) LOCATION OF WELL by legal description: (1) OWNER: Baker Latitude Longitude County E or W. WM. N or S Range City North Pourder Section State O Tax Lot 300 Lot Block (2) TYPE OF WORK Rock Crick Lane Street Address of Well (or nearest address) New Well Deepening Alteration (repair/recondition) Abandonment (3) DRILL METHOD: Auger Rotary Mud Cable Rotary Air ft. below land surface. Other Artesian pressure lb. per square inch. (4) PROPOSED USE: (11) WATER BEARING ZONES: Trigation Community Industrial Domestic Livestock Other Injection Thermal Depth at which water was first found (5) BORE HOLE CONSTRUCTION: Special Construction approval Tyes Mo Depth of Completed Well 150 SWL Estimated Flow Rate From Amount Explosives used Yes Yo Type 200 Diameter 24-sacks (12) WELL LOG: \square D \Box E Ground Elevation - \Box C Method V Other Housed 3/9" <u>bentonite</u> SWL From Material Material Backfill placed from O Size of gravel Gravel placed from (6) CASING/LINER: Plastic Welded Gauge Steel ωR 130 Liner: \Box WB. Final location of shoe(s) (7) PERFORATIONS/SCREENS: Method Perforations Material Screens Tele/pipe Slot Liner Casing Diameter Number From Completed (8) WELLTESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Artesian of this well is in compliance with Oregon water supply well construction standards.

Materials used and information reported above are true to the best of my knowledge Bailer Pump Time Drill stem at Drawdown Yield gal/min and belief. 1 hr. 400 WWC Number Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water I accept responsibility for the construction, alteration, or abandonment work Yes By whom Was a water analysis done? performed on this well during the construction dates reported above. All work Too little performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Did any strata contain water not suitable for intended use? Salty Muddy Odor Colored Other Depth of strata: