	VC	-	
DECEIVER (CLAC -		
	04234		
NOTICE TO WATER WELLICONTRACTOR 2 1965 The original and first copy of this report are to be filed with to TE ENGINEER	LL REPORT	2-20D	
STATE ENGINEER, SALEM, OREGON 97310	OREGON State Well No.	<u> </u>	
STATE ENGINEER, SALEM, OREGON 97310 STATE ON (Please type) of well completion.	e or print) G-4519 State Permit No.		
(1) OWNER:	(11) WELL TESTS: Drawdown is amount w	rater level is	
Name Gladstone School District	Was a pump test made? Yes I No If yes, by whom		
Address Gladstone, Oregon	Yield: 200 gal./min. with 5 ft. drawdown	6	
	<u> </u>	8 "	
(2) LOCATION OF WELL:	" (see test" curve attached)	- "	
	Bailer test gal./min. with ft. drawdown after hrs.		
County Clackamas Driller's well number 34 34 Section 20 T. 2S R. 2E W.M.	Artesian flow g.p.m. Date		
Bearing and distance from section or subdivision corner	Temperature of water 54° Was a chemical analysis made? \Box Yes X No (12) WFULLOG: 10"		
C	(12) WELL LOG: Diameter of well below cas	sing	
	Depth drilled 311 ft. Depth of completed well		
	Formation: Describe by color, character, size of material show thickness of aquifers and the kind and nature of th stratum penetrated, with at least one entry for each ch	and structure, and he material in each	
	stratum penetrated, with at least one entry for each ch	ange of formation.	
	MATERIAL	FROM TO	
(3) TYPE OF WORK (check):	Top soil	0 2	
New Well 🕅 Deepening 📋 Reconditioning 🗋 Abandon 🗌	Boulders	2 17	
andonment, describe material and procedure in Item 12.	Clay and gravel	17 <u>21</u> 21 25	
(4) PROPOSED USE (check): (5) TYPE OF WELL:	Broken rock	25 74	
Domestic 🔲 Industrial 🗌 Municipal 🔲 Rotary, 🖾 Driven 🗌	Gray rock	74 76	
Irrigation Test Well & Other Cable A Jetted	Broken rock interbed	76 93	
	Gray rock Black, soft, rock, some water	93 119	
(6) CASING INSTALLED: Threaded Welded	Black rock	119 127	
<u>10</u> " Diam. from0 ft. to <u>27</u> ft. Gage • <u>307</u>	Gray rock	127 155	
ft. to ft. Gage	Perforated rock, water 10 gpm	155 179	
ft. Gage	Brown perforated rock	179 181	
(7) PERFORATIONS: Perforated? Yes X No	Perforated rock, hard streaks	181 202	
Type of perforator used	Hard rock	202 226	
Size of perforations in. by in.	Soft rock with crevices, some	226 235	
perforations from ft. to ft.	Hard rock, then soft perforated	235 252	
ft. to ft.	I Soft perforated rock w/green soal	252 254	
ft. to ft.	Hard rock	254 256	
ft, to ft,	Soft rock with soap stone	256 258	
perforations from ft. to ft.	Hard rock	258 260	
SCREENS: Well screen installed? Ves X No	Soft rock w/hard streaks	260 281	
facturer's Name	Soft rock, water bearing	281 302	
Model No.	Hard rock	302 311	
Set from ft. to ft.	Work started 5-18 1965 Completed	1-6 1965	
Diam	Work started 5-1 19 6 Completed / 0 Date well drilling machine moved off of well / 0-	2	
(9) CONSTRUCTION:	(13) PUMP:	1303	
Well seal—Material used in seal <u>Concrete</u>	Manufacturer's Name		
Depth of seal	Type:	I.P	
	Water Well Contractor's Certification:		
Were any loose strata cemented off? [] Yes 🍒 No Depth	This well was drilled under my invisibilities a	and this never to	
Was a drive shoe used? \Box Yes \mathbb{Z} No Was well gravel packed? \Box Yes \Box XNo Size of gravel:	This well was drilled under my jurisdiction a true to the best of my knowledge and belief.	tha this report is	
Gravel placed from ft. to ft.	NAME A.M. JANNSEN DRILLING CO.		
Did any strata contain unusable water? 🗌 Yes 🕱 No	(Person, firm or corporation) (Type or print)		
Type of water? depth of strata	- Address 21075 S.W. Tualatin Hwy.		
Alona, Ure.			
(10) WATER LEVELS:	Drilling Machine Operator's License No. 235 & 164		
State rever 17 17. Server and State Parts			
Artesian pressure lbs. per square inch Date		, 19	
(USE ADDITIONAL SI	HEETS IF NECESSARY)		

í

Í



Jannsen Drilling Company 21075 S. W. Tualatin Valley Highway DATE: Aloha, Oregon

DATE RECEIVED:

SUBJECT:

TO:

Gladstone School District

ANALYSIS

pH Value

Well water

7.10

November 4, 1965

	parts per million
Total Solids (Residue on Evaporation)	177
Alkalinity (as CaCO ₃) Carbonate	0
Bicarbonate	110
Hardness (as CaCO3)	99.8
Silica (SiO ₂)	26.7
Calcium (Ca)	20.7
Magnesium (Mg)	
Iron (Fe) Sodium (Na)	11.8
Potassium (K)	6.8
Chloride (C1)	8.0
Sulfate (SO ₄)	10.9

REMARKS: This is a moderately hard bicarbonate type water. The iron is quite high but might be due to the water being from a new well. No mention was made of requirement to determine the percentage of sand. It was therefore not run.

CHARLTON LABORATORIES, INC. Wood BNW:lr 3c 1c

MUTUAL PROTECTION TO THE CLIENT, THE PUBLIC AND OURSELVES ALL REPORTS ARE SUBMITTED AS THE CONFIDENTIAL ATORY NOR ANY MEMBER OF ITS STAFF MAY BE USED IN CONNECTION WITH T OF ANY PRODUCT WITHOUT WRITTEN AUTHORIZATION. PROPERTY OF THE CLIENT SITHER REPORTS NOR THE NAME OF THIS LABORATORY

ackama ĝ 5 Gladstore School District Supply Well Pump test curve GINEER Έ STAT E SALEM OREGO A.M. Jannsen Drilling Co. 21075 500 Tualatu Valley Huy Aloha, Oragon ¶1 79' states 6.P.M.