

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Westerberg Drilling, Inc.
36728 S. Kropf Rd.
Molalla, OR 97038

WELL I.D. # L 99824

START CARD # 201566

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number _____
Name Gingerich Farms LLC
Address PO Box 910
City Canby State OR Zip 97013

(2) TYPE OF WORK New Well
 Deepening Alteration (repair/recondition) Abandonment Conversion

(3) DRILL METHOD
 Rotary Air Rotary Mud Cable Auger Cable Mud
 Other _____

(4) PROPOSED USE
 Domestic Community Industrial Irrigation
 Thermal Injection Livestock Other _____

(5) BORE HOLE CONSTRUCTION Special Construction: Yes No
Depth of Completed Well 315 ft.
Explosives used: Yes No Type _____ Amount _____

BORE HOLE			SEAL		
Diameter	From	To	Material	From	To
Original	Well	Log	CLAC	18360	
10"	0	315	Original		

How was seal placed: Method A B C D E
 Other Original Undisturbed

Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from 248 ft. to 315 ft. Size of gravel 6/9 CSS

(6) CASING/LINER

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 10"	+1.5	297	.250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From CLAC 18360							
Bottom of 10" casing							
Conf. w/magnetic top							
Liner: 8"	249	289	.250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8"	312	315	.250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used Inside Outside None
Final location of shoe(s) Original

(7) PERFORATIONS/SCREENS
 Perforations Method V-Wire Wrapped
 Screens Type _____ Material Stainless

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
289	312	.060		8"	PS	<input type="checkbox"/>	<input type="checkbox"/>

(8) WELL TESTS: Minimum testing time is 1 hour
 Pump Bailer Air Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
500	119		4 hrs

Temperature of water 56 Depth Artesian Flow Found _____
Was a water analysis done? Yes By whom _____
Did any strata contain water not suitable for intended use? Too little
 Salty Muddy Odor Colored Other _____
Depth of strata: _____

(9) LOCATION OF WELL (legal description)
County Clackamas
Tax Lot 800 Lot _____
Township 4 S Range 1 E WM
Section 35 SE 1/4 SE 1/4

Lat _____ ° ' " or _____ (degrees or decimal)
Long _____ ° ' " or _____ (degrees or decimal)

Street Address of Well (or nearest address) 29995 S. Ellaha Rd.
Canby, OR 97013

(10) STATIC WATER LEVEL
44' 3.5" ft. below land surface. Date 02/24/10
_____ ft. below land surface. Date _____
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES
Depth at which water was first found Original

From	To	Estimated Flow Rate	SWL
Original	See CLAC	18360	

(12) WELL LOG Ground Elevation _____

Material	From	To	SWL
Sand Black Course	Original	312	
Clay Grey Sticky	312	315	

This well had a bad sand pumping problem. The original well screen was removed, well cleaned out/deepened and a new screen along with filter pack was installed.

RECEIVED

MAR 1 2010

WATER RESOURCES DEPT
SALEM, OREGON

Date Started 01/20/10 Completed 02/26/10

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number _____ Date _____

Signed _____

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 688 Date 03/10/10

Signed Steven N. Stadler