STATE OF ODECON	CI & C 72270	WELL I.D. LABEL# L	25660	Page 1 of 1
STATE OF OREGON WATER SUPPLY WELL REPORT	CLAC 73278		035359	
(as required by ORS 537.765 & OAR 690-205-0210)	7/22/2017	ORIGINAL LOG #	333339	
(1) LAND OWNER Owner Well I.D.			J	
(1) LAND OWNER Owner Well I.D. First Name DAVID Last Name		CATION OF WELL (legal des	cription)	
COUNTRY CLUB WATER DISTRICT		LACKAMAS Twp 2.00 S N/S	-	E/W WM
Address PO BOX 168 City BRIGHTWOOD State OR Zip 97011		SE 1/4 of the NE 1/4		
Alteration (complete 2a & 10) Abandonment(c	complete 5a)	Number' or		DMS or DD
(2a) PRE-ALTERATION	Long	' or		DMS or DD
Dia + From To Gauge Stl Plstc Wld Thrd Casing:		• Street address of well (Neares	st address	
	21323 CC	OUNTRY CLUB ROAD		
Material From To Amt sacks/lbs Seal:				
(3) DRILL METHOD	(10) ST	ATIC WATER LEVEL		
Rotary Air Rotary Mud Cable Auger Cable Mud	Existi	ng Well / Pre-Alteration	SWL(psi) +	SWL(ft)
Reverse Rotary Other		leted Well 7/19/2017	┼───┤╞╬╴	192
(4) PROPOSED USE Domestic Irrigation Community			Dry Hole?	1)2
Industrial/ Commericial Livestock Dewatering	WATER B	EARING ZONES Depth water	was first found 27	4.00
Thermal Injection Other	SWL D	-	ow SWL(psi) +	
(5) BORE HOLE CONSTRUCTION Special Standard	(Attach copy) 7/19/20			
Depth of Completed Well <u>381.00</u> ft.	(Attach copy) //19/20	17 274 374 60	 -	192
BORE HOLE SEAL	sacks/			
	Amt lbs			
	3100 P			
6 98 381 Calculated 2				
Calculated	(11) WE	LL LOG Ground Elevation		
How was seal placed: Method $\square A \square B \boxtimes C \square D$	E	Material	From	То
Other	top soil		0	3
Backfill placed from ft. to ft. Material		y w/ cobbles	3	12
Filter pack from ft. to ft. Material Size	multi colo	red rock rock/fractured	12	16 21
Explosives used: Yes Type Amount	multi colo		21	82
(5a) ABANDONMENT USING UNHYDRATED BENTON	ITE black basa	lt	82	152
Proposed Amount Actual Amount	red lava ro		152	166
(6) CASING/LINER	black basa		166	249 262
Casing Liner Dia + From To Gauge Stl Plstc	Wid Thrd	red black rock	249	311
		grey basalt	311	314
	multi colo	red rock	314	320
		lt	320	381
Shoe Inside Outside Other Location of shoe(s) 9	8			
Temp casing \overline{X} Yes Dia 10 From + 0 To 11				
(7) PERFORATIONS/SCREENS				
Perforations Method				
Screens Type certalok Material pvc		rted <u>7/17/2017</u> Comple	eted 7/19/2017	
Perf/ Casing/ Screen Scrn/slot Slot # of Screen Liner Dia From To width length slots		ed) Water Well Constructor Certificat	tion	
Screen Liner 4 321 381 .32	I certify t	hat the work I performed on the const	truction, deepening	, alteration, or
		nent of this well is in compliance w		
		on standards. Materials used and inform f my knowledge and belief.	mation reported abo	ove are true to
	License N			
(8) WELL TESTS: Minimum testing time is 1 hour				
$\bigcirc Pump \qquad \bigcirc Bailer \qquad \bigcirc Air \qquad \bigcirc Flowing A$	Artesian			
°		Water Well Constructor Certification		
		esponsibility for the construction, deep		or abandonment
		ormed on this well during the construction		
		during this time is in compliance		
Temperature <u>54</u> °F Lab analysis Yes By 6		construction standards. This report is true to the best of my knowledge and belief.		
Water quality concerns? Yes (describe below) TDS amount 132ppm		License Number <u>1771</u> Date <u>7/22/2017</u>		
		GEORGE YOUNGBERG (E-filed)		
		fo (optional) Youngberg Pump & Well	Drilling ph. 503-63	30-3970

ORIGINAL - WATER RESOURCES DEPARTMENT THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK Form Version: