

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

COLU 55703

WELL I.D. LABEL# L

132799
START CARD # 1049416
ORIGINAL LOG #

2/1/2021

(1) LAND OWNER

Owner Well I.D.
First Name Last Name
Company COLUMBIA HILLS HOME OWNER'S ASSOCIATION
Address 50606 CRYSTAL RIDGE ROAD
City SCAPPOOSE State OR Zip 97056

(2) TYPE OF WORK

[X] New Well [] Deepening [] Conversion
[] Alteration (complete 2a & 10) [] Abandonment (complete 5a)

(2a) PRE-ALTERATION

Casing: Dia + From To Gauge Stl Plstc Wld Thrld
Material From To Amt sacks/lbs
Seal:

(3) DRILL METHOD

[X] Rotary Air [] Rotary Mud [] Cable [] Auger [] Cable Mud
[] Reverse Rotary [] Other

(4) PROPOSED USE

[X] Domestic [] Irrigation [X] Community
[] Industrial/ Commercial [] Livestock [] Dewatering
[] Thermal [] Injection [] Other

(5) BORE HOLE CONSTRUCTION

Depth of Completed Well 200.00 ft. Special Standard [] (Attach copy)

Table with columns: Dia, From, To, Material, SEAL, Amt, sacks/lbs. Rows include Bentonite Chips and Cement with 5% Bento.

How was seal placed: Method [] A [] B [X] C [] D [] E

[X] Other POUR

Backfill placed from ft. to ft. Material

Filter pack from ft. to ft. Material Size

Explosives used: [] Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount Actual Amount

(6) CASING/LINER

Table with columns: Casing, Liner, Dia, From, To, Gauge, Stl, Plstc, Wld, Thrld. Includes material and shoe information.

Shoe [] Inside [] Outside [] Other Location of shoe(s)

Temp casing [] Yes Dia From + To

(7) PERFORATIONS/SCREENS

Perforations Method

Screens Type wound Material s.s.

Table with columns: Perf/ Screen, Casing/ Liner, Dia, From, To, Scrn/slot width, Slot length, # of slots, Tele/ pipe size.

(8) WELL TESTS: Minimum testing time is 1 hour

[X] Pump [] Bailer [] Air [] Flowing Artesian

Table with columns: Yield gal/min, Drawdown, Drill stem/Pump depth, Duration (hr). Rows show test results.

Temperature 51 °F Lab analysis [] Yes By

Water quality concerns? [] Yes (describe below) TDS amount 211 ppm

Table with columns: From, To, Description, Amount, Units.

(9) LOCATION OF WELL (legal description)

County COLUMBIA Twp 3.00 N N/S Range 2.00 W E/W WM
Sec 22 NE 1/4 of the SW 1/4 Tax Lot 9600
Tax Map Number Lot
Lat 45.72513515 DMS or DD
Long -122.92009502 DMS or DD
[] Street address of well [X] Nearest address

LOT 11 SAGE STREET SCAPPOOSE OR

(10) STATIC WATER LEVEL

Table with columns: Existing Well / Pre-Alteration, Date, SWL(psi), SWL(ft). Row shows 12/1/2020 and 30.

WATER BEARING ZONES

Depth water was first found 45.00

Table with columns: SWL Date, From, To, Est Flow, SWL(psi), SWL(ft). Row shows 12/1/2020, 45, 55, 100, 30.

(11) WELL LOG

Ground Elevation

Table with columns: Material, From, To. Rows include brn clay, gray clay stone, basalt blk, blue gray sandstone /claystone.

Date Started 10/14/2020 Completed 1/29/2021

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards.

License Number Date

Signed

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above.

License Number 1480 Date 2/1/2021

Signed ARTHUR MCMULLEN (E-filed)

Contact Info (optional) 503 397 2356

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

COLU 55703

2/1/2021

Map of Hole

