RRESOURCES DEPWELL I.D.# WATER SUPPLY WELL REPORT SALEM, OREGON STATE OF OREGON (START CARD) # <u>93549</u> crop (as required by ORS 537.765) 50239 Instructions for completing this report are on the last page of this form. (9) LOCATION OF WELL by legal description: Well Number (1) OWNER: County CROSK Latitude Longitude Name J/M Or W. WM N or Range Township 1/4 Zip Subdivision Tax Lot <u>40/</u> Lot Block (2) TYPE OF WORK Street Address of Well (or nearest address) 281486 New Well Deepening Alteration (repair/recondition) Abandonment PRINEVILLE (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Mud Cable Rotary Air ft. below land surface. Other Artesian pressure lb. per square inch. (4) PROPOSED USE: (11) WATER BEARING ZONES: ☐ Irrigation Community Industrial Domestic Other Livestock Injection Thermal Depth at which water was first found (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well Estimated Flow Rate From Amount Explosives used Yes No Type Sacks or pounds Material Diameter (12) WELL LOG: Ground Elevation Method \square B Y Other HOLE PLUG POURE **SWL** From To Material ft. Material Backfill placed from E COBBI တ Size of gravel Gravel placed from (6) CASING/LINER: Welded Threaded Plastic Gauge Steel From To ¥ OCK 409 ROCK Final location of shoe(s) (7) PERFORATIONS/SCREENS: MACHINE Perforations Method Material 3724 Screens Tele/pipe Casing Diameter Completed (8) WELLTESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Air Artesian Bailer Pump of this well is in compliance with Oregon water supply well construction standards. Drill stem at Time Materials used and information reported above are true to the best of my knowledge Yield gal/min Drawdown 300 1 hr. and belief. WWC Number 409 Date Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work Yes By whom Was a water analysis done? Too little performed during this time is in compliance with Oregon water supply well Did any strata contain water not suitable for intended use? construction standards. This report is true to the best of my knowledge and belief Salty Muddy Odor Colored Other WWC Number / 5 Depth of strata: ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR

THIRD COPY-CUSTOMER

APR 22 1997