RECEIVED (as required by ORS 537.765) 1001 (9) LOCATION OF WELL by legal description: (1) OWNER: Name Longitude Address New Well ☐ Deepen Recondition □ Abandon Street Address of Well (or nearest address) \_ **WRILL METHOD:** (10) STATIC WATER LEVEL: Rotary Air Cable Cable ☐ Rotary Mud ft. below land surface. U. Other PROPOSED USE: lb. per square inch. Artesian pressure (11) WATER BEARING ZONES: Community Industrial Irrigation ☐ Thermal ☐ Injection (5) BORE HOLE CONSTRUCTION: Depth at which water was first found From To Estimated Flow Rate Explosives used Yes No Type HOLE Amount sacks or pounds Material (12) WELL LOG: Ground elevation How was seal placed: Method A From To **SWL**  Material 12 Backfill placed from\_ Material Gravel placed from\_\_\_\_\_ ft. to\_ Size of gravel (6) CASING/LINER: Welded Threaded Gauge | Steel Liner: Final location of shoe(s) (7) PERFORATIONS/SCREENS: Perforations Method Screens Material Tele/pipe From To Number Diameter Casing (8) WELL TESTS: Minimum testing time is 1 hour Date started Completed Flowing Air (unbonded) Water Well Constructor Certification: ☐ Pump ☐ Bailer ☐ Artesian I certify that the work I performed on the construction, alteration, or abandon-Yield gal/min Drill stem at Time Drawdown ment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief. 1 hr. WWC Number Signed . (bonded) Water Well Constructor Certification:

Depth of strata: \_\_\_\_\_\_ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT

Depth Artesian Flow Found

Temperature of Water 50°

Did any strata contain water not suitable for intended use?

Salty Muddy Odor Colored Other

SECOND COPY - CONSTRUCTOR

is true to the best of my knowledge and belief.

THIRD COPY - CUSTOMER

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed

during this time is in compliance with Oregon well construction standards. This report

9809C 10/91