KLAM 50155 / STATE OF OREGON /WATER SUPPLY WELL REPORT

PECEVIE KLAM 50155

DEC 1 3 1995

415 106 4 BB (START CARD)# 83004

(as required by ORS 537.765) JUNICES DEPT. Instructions for completing this report are on the last page of this form. SALEM, OREGON OF WELL by legal description: Well Number Longitude N or S Range E or W. WM. Block Subdivision (2) TYPE OF WORK Street Address of Well (or nearest address) 20606 Cement anka New Well Deepening Alteration (repair/recondition) Abandonment (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Air Rotary Mud Cable Auger Other ft. below land surface. (4) PROPOSED USE: lb. per square inch. Artesian pressure (11) WATER BEARING ZONES: 1 Ifrigation □ Domestic Community Industrial Other ☐ Thermal Injection Livestock (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes No Depth of Completed Well 356ft Estimated Flow Rate SWL Explosives used Yes No Type Amount HOLE SEAL Diameter Material Sacks or pounds (12) WELL LOG: How was seal placed: Method \Box E **Ground Elevation** Other SWL Backfill placed from From То fi. to Material 124/2 Z86 300 ft. Gravel placed from Size of gravel (6) CASING/LINER: Diameter Gauge Steel Plastic Welded Threaded Casing_ \Box Liner: Final location of shoe(s) (7) PERFORATIONS/SCREENS: Perforations Method Screens Material Slot Tele/pipe Diameter Casing Liner From \Box Completed (8) WELLTESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Pump Bailer Air Artesian of this well is in compliance with Oregon water supply well construction standards. Drawdown Drill stem at Time Yield gal/min Materials used and information reported above are true to the best of my knowledge 2hr. and belief. WWC Number Date Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water_ I accept responsibility for the construction, alteration, or abandonment work Was a water analysis done? Yes By whom performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Salty Muddy Odor Colored Depth of strata: ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER