MARI BECFIVED 20050

STATE OF OREGON

WATER SUPPLY WELL REPORT OCT 1 6 1995

085/0101300

RECEIVED

Instructions for completing this report strates the first frage of this forms OVER THE COUNTERT CARD)# SAL EMber OREGON (9) LOCATION OF WELL by legal description: (1) OWNER County MALION Latitude Longitude Name E or W. WM. N or S Range_ 1/4 State Ore HUMSVIL Subdivision Block (2) TYPE OF WORK Lot Street Address of Well (or nearest address) 9613 New Well Deepening Alteration (repair/recondition) Abandonment Aumsville (3) DRILL METHOD: Rotary Mud Auger Rotary Air ft. below land surface. Other lb. per square inch. (4) PROPOSED USE: Artesian pressure (11) WATER BEARING ZONES: Community Industrial Domestic Thermal Injection Livestock Depth at which water was first found (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well 195ft Estimated Flow Rate **SWL** From Explosives used Yes No Type HOLE SEAL From Diameter 30 Sects (12) WELL LOG: □В $\square D$ How was seal placed: Method Ground Elevation Other SWL From Material ft. Material Backfill placed from ft. to 0 3 Size of gravel P-Grave Gravel placed from 150 ft. to 195 ft. 21 (6) CASING/LINER: ک Threaded Gauge Steel Plastic Welded 25 X 29 4 96 <u>78</u> Liner: 98 Final location of shoe(s) (7) PERFORATIONS/SCREENS: 10 Perforations Method Material Screens Type Tele/pipe Liner Number Diameter Casing From None П 30 8-2-95 Completed (8) WELLTESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Bailer Air Artesian Pump of this well is in compliance with Oregon water supply well construction standards. Time Drill stem at Materials used and information reported above are true to the best of my knowledge Yield gal/min 1 hr. and belief. WWC Number Signed (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water 53 I accept responsibility for the construction, alteration, or abandonment work Yes By whom Was a water analysis done? performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well Did any strata contain water not suitable for intended use? Too little construction standards. This report is true to the best of my knowledge and belief Salty Muddy Odor Colored Other Depth of strata: