

MARI 58604  
MARI 58604

STATE OF OREGON  
WATER SUPPLY WELL REPORT  
(as required by ORS 537.765)

WELL I.D. # L 59626

START CARD # W-138760

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number 33-04  
Name Cedarwood Nursery  
Address 13300 Cedarwood Road  
City Aurora State Oregon Zip 97002

(2) TYPE OF WORK  New Well  
 Deepening  Alteration (repair/recondition)  Abandonment  Conversion

(3) DRILL METHOD  
 Rotary Air  Rotary Mud  Cable  Auger  Cable Mud  
 Other

(4) PROPOSED USE  
 Domestic  Community  Industrial  Irrigation  
 Thermal  Injection  Livestock  Other

(5) BORE HOLE CONSTRUCTION Special Construction:  Yes  No  
Depth of Completed Well 144 ft.  
Explosives used:  Yes  No Type \_\_\_\_\_ Amount \_\_\_\_\_

BORE HOLE			SEAL			Sacks or Pounds	
Diameter	From	To	Material	From	To		
12	0	65	Bentonite	0	18	21	sacks
8	65	144	Cement w/ 3% bent.	18	65	26	sacks

How was seal placed: Method  A  B  C  D  E  
 Other Bentonite  
Backfill placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Material \_\_\_\_\_  
Gravel placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Size of gravel \_\_\_\_\_

(6) CASING/LINER

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 8	+2	133	250	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Liner:				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Drive Shoe used  Inside  Outside  None  
Final location of shoe(s) \_\_\_\_\_

(7) PERFORATIONS/SCREENS  
 Perforations Method \_\_\_\_\_ Type Telescope Material Stainless  
 Screens

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
128	144	60		8	Tele	<input type="checkbox"/>	<input type="checkbox"/>

(8) WELL TESTS: Minimum testing time is 1 hour  
 Pump  Bailer  Air  Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
90	18		2 hours

Temperature of water 53 Depth Artesian Flow Found \_\_\_\_\_  
Was a water analysis done?  Yes By whom \_\_\_\_\_  
Did any strata contain water not suitable for intended use?  Too little  
 Salty  Muddy  Odor  Colored  Other \_\_\_\_\_  
Depth of strata: \_\_\_\_\_

(9) LOCATION OF WELL (legal description)  
County Marion  
Tax Lot 300 Lot \_\_\_\_\_  
Township 4 S Range 1 W WM  
Section 11 nw 1/4 nw 1/4

Lat \_\_\_\_\_° \_\_\_\_\_' \_\_\_\_\_" or \_\_\_\_\_ (degrees or decimal)  
Long \_\_\_\_\_° \_\_\_\_\_' \_\_\_\_\_" or \_\_\_\_\_ (degrees or decimal)

Street Address of Well (or nearest address) 13300 Cedarwood Road  
Aurora, Oregon 97002

(10) STATIC WATER LEVEL  
61 ft. below land surface. Date 12-3-04  
\_\_\_\_\_ ft. below land surface. Date \_\_\_\_\_  
Artesian pressure \_\_\_\_\_ lb. per square inch Date \_\_\_\_\_

(11) WATER BEARING ZONES  
Depth at which water was first found 108

From	To	Estimated Flow Rate	SWL
23	31	?	26
<u>108</u>	<u>142</u>	<u>90</u>	<u>61</u>

(12) WELL LOG Ground Elevation \_\_\_\_\_

Material	From	To	SWL
Silty clay-brown	0	23	
Sand-silt-brown	23	31	26
Clay-brown	31	48	
Clay-grey	48	108	
Gravel-sand-grey	108	142	61

RECEIVED  
DEC 20 2004  
WATER RESOURCES DEPT  
SALEM, OREGON

RECEIVED  
FEB 14 2005  
WATER RESOURCES DEPT  
SALEM, OREGON

Date Started 11-10-04 Completed 12-3-04

(unbonded) Water Well Constructor Certification  
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.  
WWC Number \_\_\_\_\_ Date \_\_\_\_\_  
Signed \_\_\_\_\_

(bonded) Water Well Constructor Certification  
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.  
WWC Number 1 Date 12-07-04  
Signed Ronald L. McInerney