MARI 61020

STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765)

R. Stadell & Sons Well & Pump Inc. 4385 Stadell Lane NE Silverton, OR 97381

WELL LD. # L	78658	

START CARD # 196260

Instructions for completing this report are on the last page of this form.

and decided for completing this report are on the last page of this for in-			
(1) LAND OWNER Well Number	County Marion		
	Tax Lot 200 Lot		
City Yakima State WA Zip 98902	Township 8 S Range 2 W WM Section 12 SE 1/4 NW 1/4		
(2) TYPE OF WORK ☐ New Well ☐ Deepening ☑ Alteration (repair/recondition) ☐ Abandonment ☐ Conversion			
(3) DRILL METHOD ☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud ☑ Other repair damaged well head	Street Address of Well (or nearest address) 3515 Howell Prairie Rd. Salem, OR 97317		
(4) PROPOSED USE Domestic Community Industrial Irrigation Thermal Injection Livestock Other	(10) STATIC WATER LEVEL 42 ft. below land surface. Date 9-26-07 ft. below land surface. Date		
(5) BORE HOLE CONSTRUCTION Special Construction: Yes No Depth of Completed Well 320 ft. Explosives used: Yes No Type Amount	Artesian pressure lb. per square inch Date (11) WATER BEARING ZONES Depth at which water was first found Original		
BORE HOLE SEAL			
Diameter From To Material From To Sacks or Pounds Original Bentonite 0 9 11 sacks	From To Estimated Flow Rate SWL		
How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E ☐ Other Bentonite placed dry	(12) WELL LOG Ground Elevation		
Backfill placed from ft. to ft. Material	Material From To SWL		
Gravel placed from ft. to ft. Size of gravel	See Mari 53151 for original log.		
(6) CASING/LINER	Original Well ID tag L20449 became lost when well head was		
Diameter From To Gauge Steel Plastic Welded Threader	struck by farm equipment.		
Casing: 10" +2 6' .250 Z	Well head was damaged by farm		
	equipment. We cut off approx. 8'		
	of damaged casing and replaced with new casing, resealed		
Diameter From To Gauge Steel Plastic Welded Threaded Casing: 10" +2 6' .250 \frac{1}{2} \qquad \qquad \qquad \qquad \qquad \qquad \qquad \qqqq \qqqqq \qqqq \qqqq \qqqq \qqqq \qqqq \qqqq \qqqq \qqqq \qqqqq	with new casing, resealed		
	with bentonite chips and attached		
Drive Shoe used Inside Outside None	new Well ID tag. 0CT 0 3 2007		
Final location of shoe(s)			
ritial location of shoe(s)	WATER RESOURCES DEPT		
(7) PERFORATIONS/SCREENS	SALEM ODCON		
Perforations Method	SALEM OREGON		
Screens Type Material			
From To Slot Number Diameter Tele/pipe Casing Liner	Date Started 9-26-07 Completed 9-26-07		
Size Size Casing Enter	(unbonded) Water Well Constructor Certification		
	I certify that the work I performed on the construction, deepening, alteration, or		
	abandonment of this well is in compliance with Oregon water supply well		
	construction standards. Materials used and information reported above are true to the best of my knowledge and belief.		
	the best of my knowledge and belief.		
	WWC Number Date		
(8) WELL TESTS: Minimum testing time is 1 hour ☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian	Signed		
Yield gal/min Drawdown Drill stem at Time	(bonded) Water Well Constructor Certification		
N/A	I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported		
	above. All work performed during this time is in compliance with Oregon water		
Temperature of water Depth Artesian Flow Found	supply well construction standards. This report is true to the best of my knowledge and belief.		
Was a water analysis done? Yes By whom	and belief.		
Did any strata contain water not suitable for intended use?	WWC Number 1487 Date 10-2-07		
Salty Muddy Odor Colored Other			
Depth of strata:	Signed Hanil Date 10-2-07		