STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

PECEMED

MOV 1 3 1995

015/03E/22DB

WATER RESOURCES DEPT CARD) # Instructions for completing this report are on the last page of this form. (9) LOCATION OF WELL by legal description: Well Number County //u//. Latitude Coans Longitude N or S Range 1/4 Subdivision Block Lot Street Address of Well (or nearest address) New Well Deepening Alteration (repair/recondition) Abandonment (3) DRILL METHOD: Rotary Mud Cable Auger Rotary Air ft. below land surface. Other lb. per square inch. (4) PROPOSED USE: Artesian pressure (11) WATER BEARING ZONES: Community Irrigation Demestic Industrial Other Thermal Injection Livestock Depth at which water was first found 140 (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well **Estimated Flow Rate** Explosives used Yes No Type From 140 5 TO 10GPM Diameter (12) WELL LOG: Method Ground Elevation How was seal placed: **SWL** From To Material Material Backfill placed from ft. to ft. Size of gravel Gravel placed from (6) CASING/LINER: Threaded Final location of shoe(s) 12 (7) PERFORATIONS/SCREENS: Perforations Material Tele/pipe (8) WELL TESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Artesian Air Pump of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge Yield gal/min and belief. WWC Number Date Signed Depth Artesian Flow Found (bonded) Water Well Constructor Certification: Temperature of water 5 I accept responsibility for the construction, alteration, or abandonment work Yes By whom Was a water analysis done? performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well Did any strata contain water not suitable for intended use? Salty Muddy Odor Colored Other construction standards. This report is true to the best of my knowledge and belief Depth of strata: