

McEwen Butte
1972 edition
WH Seal

$$\begin{array}{r} 118^{\circ}15' \\ 43^{\circ}30' \end{array}$$

R 36/E

400000m. E.

R 37 E

402 12'30"

40

4816000m.N.

4815

4814

4813

27'30"

4812

4811

BUCKMOUNTAIN

HARNEY CO
MALHEUR CO

71908

"CERTIFICATE NO.

Application No.

Permit No.

RECEIVED

JAN 3 1995

WATER HEAT
SALEM, OREGON

Springs

No.

Springs

Creek

Luce
Hot Springs

3500
Woonsocket

A map showing the location of Spurlock Ranch. A line labeled "PACIFIC" runs diagonally from the top left. A dashed line, possibly a road or boundary, runs parallel to it. A point is marked on this dashed line and labeled "Spurlock Ranch". The year "1907" is written in the top right corner.

UNIÓN

McEwe
Ranch

en 32
(54)

16

1