

9/10/2026

START CARD #

1083499

ORIGINAL LOG #

(2a) PRE-ALTERATION

[illegible]

(5) BORE HOLE CONSTRUCTION

BORE HOLE			SEAL			sacks/ lbs	
Dia	From	To	Material	From	To		Amt
			Calculated				
			Calculated				
			Calculated				
			Calculated				

FILTER PACK		Material	Size
From	To		

(6) CASING/LINER

[illegible]

(7) PERFORATIONS/SCREENS

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Type of Test	Yield (gal/min)	Drawdown	Drill Stem/ Pump Depth	Duration (hr)

Water Quality Concerns

[illegible]

(10) STATIC WATER LEVEL

[illegible]

(11) WELL LOG

[illegible]

Name of person(s) who assisted with construction and Trainee License # / Helper #

Assistant Name	Type	#
KALEB BRADLEY	HELPER WATER	8888995
CJ NUGENT	WATER AND MONITORING	1974

Comments/Remarks

Did not find deeper water so we abandoned the well. TDS of Water bearing zone was 239, but the deeper we went the higher the TDS was going up. Hole Abandon. Website would not let me submit a map.