#15

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

COOS 355

RECEIVED
MAR 25 1991
WATER RESOURCES DEPT

305/15W/12 bc

(START CARD) # 22965

(1) OWNER: Well Number:
Name Tartan Farms LTD c/o steve warnock
Address RT 1 Box 1463
City Bandon State OR Zip 97411

(2) TYPE OF WORK:
☑ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD
☑ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes ☐ No ☑ Depth of Completed Well 67 ft.
Explosives used Yes ☐ No ☑ Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
9	0	20	Bent	20	0	12 1/4
6 1/2	20	67				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☑ Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	4 1/2	+2	27	SDR26	☐	☑	☑	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
☐ Perforations Method Hydrophilic
☑ Screens Type plastic Material PVC

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
27	67	.010		4 1/2		☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
30		67	1 hr.

Temperature of water 52° Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County COOS Latitude Longitude
Township 30 N or S Range 15 E or W WM.
Section 12 SW ¼ NW ¼
Tax Lot 1364900 Block Subdivision
Street Address of Well (or nearest address) Croft Rd
RT 1 Box 1463 Bandon

(10) STATIC WATER LEVEL:
23 ft. below land surface. Date 3-8-91
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 25

From	To	Estimated Flow Rate	SWL
25	67	30 gpm	23

(12) WELL LOG: Ground elevation

Material	From	To	SWL
Brown top soil w/wood	0	3	
Brown sandy clay	3	23	
Brown sand med	23	63	23

Date started 3-7-91 Completed 3-8-91

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 1381
Signed Ron Beaugh Date 3-18-91

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 3/88