

Clean Well to Bottom (Note are 8" Bit would not fit so we sent a 6" bit down hit slug about 320 cleaned out to 350 note 350 was bottom
Drilled to 360 to make sure that it was not just a hard cave. tested flow at 12 Gmp. when pulling out hole caved back in to 289 with brown running clay most likley were the water is coming in at static 224. If this well was to be repaired i would try a 7.5 Bit and then if it fit down 6" liner or if it dose not go try a 5" liner no guarantees on either way woul