ORIGINAL
File Original and Duplicate with the STATE ENGINEER, SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON

RECEIVED
STATE ENGINEER
SALEM, OREGON

267 CURR

State Well No. 36/14w-30A (1)
State Permit No. 6704

(1) OWNER:
Name City of Gold Beach
Address Gold Beach, Oregon

(2) LOCATION OF WELL:
County Curry Owner's number, if any—
NE ¼ NE ¼ Section 30 T. 36 S R. 14 W.M.
Bearing and distance from section or subdivision corner
321.41 ft. S and 481.81 ft W. from N.E. Corner Section 30 Twp 36 S. Range 14 W.

(3) TYPE OF WORK (check):
New Well [X] Deepening [ ] Reconditioning [ ] Abandon [ ]
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):
Domestic [ ] Industrial [ ] Municipal [X]
Irrigation [ ] Test Well [ ] Other [ ]

(5) TYPE OF WELL:
Rotary [ ] Driven [ ]
Cable [X] Jetted [ ]
Dug [ ] Bored [ ]

(6) CASING INSTALLED: Threaded [ ] Welded [X]
10" Diam. from X 7'5" ft. to 39'2½" ft. Gage .365
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? [X] Yes [ ] No
Type of perforator used Mills Knife
SIZE of perforations 3/8 in. by 1¼ in.
240 perforations from 15.0 ft. to 33.0 ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed [ ] Yes [X] No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Was well gravel packed? [ ] Yes [X] No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? [X] Yes [ ] No To what depth? 2 ft.
Material used in seal— concrete slab
Did any strata contain unusable water? [X] Yes [ ] No
Type of water? serpentine Depth of strata 35' to 41'
Method of sealing strata off 5' concrete plug

(10) WATER LEVELS:
Static level 10 ½ ft. below land surface Date 10/20/57
Artesian pressure lbs. per square inch Date

Log Accepted by: Date Nov 8, 1957
[Signed] Thomas B. Ayres (Owner)
Mayor of Gold Beach.

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? [X] Yes [ ] No If yes, by whom? Roy Erickson
Yield: 225 gal./min. with 11½ ft. drawdown after 24 hrs.
" " " "
" " " "
Bailer test None gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water 54% Was a chemical analysis made? [ ] Yes [ ] No

(12) WELL LOG: Diameter of well 10 inches.
Depth drilled 41 ft. Depth of completed well 36 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Brown top soil	0	4
Brown soil and coarse gravel	4	8
Coarse sand and gravel with small boulders	8	13
Fine sand and gravel	13	14
Coarse gravel and some sand	14	30
Small boulders and fine gravel	30	35
Gray soft serpentine	35	41

Work started Oct. 16 1957 Completed Nov. 8 1957

(13) PUMP:
Manufacturer's Name Layne & Bowler
Type: deep well turbine H.P. 25

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Donald E. Barrington (Person, firm, or corporation) (Type or print)
Address Rt. 1 Box 63 Gold Beach, Oregon
Driller's well number 14
[Signed] Donald E. Barrington (Well Driller)
License No. 201 Date Nov. 8, 1957

(USE ADDITIONAL SHEETS IF NECESSARY)