RECEIVED CURR 51091

MAY 1 9 2004

WATER RESOURCES DEPT
SALEM, OREGON

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

32-15-4

WELL I.D. # L 66595

START CARD # 163989

(1) LAND OWNER Well Number 974

Name Bussmann Cranberry Company

Address PO Box 211

City Sixes State OR Zip 97476

(2) TYPE OF WORK

☐ New Well ☐ Deepening ☒ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:

☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger

☐ Other

(4) PROPOSED USE:

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation

☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 80' 6"

Explosives used ☐ Yes ☒ No Type Amount TOC

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
8"	0	80'	Previously Installed W/O Disturbed			

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☐ Other

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	8"	+1	54'11	250	☒	☐	☒	☐
	Previously Installed W/O Disturbed				☐	☐	☐	☐
					☐	☐	☐	☐
	6"	70'5	80'2	250	☒	☐	☐	☐
Liner:	Tai	Pipe			☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

☐ Perforations Method Telescope

☒ Screens Type Johnson Material Stainless Steel

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
53'11	59'10	.035	0	8"	Tele	☐	☐
59'10	65'1"	.040		8"	Tele	☐	☐
65'1	70'4"	.035		8"	Tele	☐	☐
Previously Installed W/O Disturbed							☐

(8) WELL TESTS: Minimum testing time is 1 hour

☒ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
250	10'	60'	1 hr.

Temperature of water 52° Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata:

Bandon Well & Septic Co., Inc.

(9) LOCATION OF WELL by legal description:

County Curry Latitude Longitude

Township 32 N or S Range 15 E or W WM.

Section 4 NW 1/4 SW 1/4

Tax Lot 3001 Lot Block Subdivision

Street Address of Well (or nearest address) 92462 Childers Rd. Sixes

(10) STATIC WATER LEVEL:

32' 4" ft. below land surface. Date 5/7/04

Artesian pressure lb. per square inch Date

(11) WATER BEARING ZONES:

Depth at which water was first found 32' 4

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Well originally Drilled 10/13/93.			
Removed Pump. Surged & Jetted Screen with air & water due to decrease in flow.			
Removed Fine sand and developed until Clear			
Reinstalled Pump			

Date started 5/7/04 Completed 5/7/04

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number 1759

Signed Chris Reesy Date 5/12/04

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1493

Signed Jon Mackey McGuire Date 5/12/04

ORIGINAL – WATER RESOURCES DEPARTMENT FIRST COPY – CONSTRUCTOR SECOND COPY – CUSTOMER