STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.545 & 537.765 and OAR 690-205-0210)

CURR 53043
1/18/2022

WELL I.D. LABEL# L 110222
START CARD # 1055401
ORIGINAL LOG # CURRY 52469

(1) LAND OWNER

Owner Well I.D. 1990
First Name JOHN Last Name YOST
Company SILVER SPRINGS RV PARK
Address 9890 BODEGA HWY
City SEBASTOPOL State CA Zip 95472

(2) TYPE OF WORK

☐ New Well ☐ Deepening ☐ Conversion ☒ Alteration (complete 2a & 10) ☐ Abandonment(complete 5a)

(2a) PRE-ALTERATION

	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
Casing:	6		0	5.5	.250	◉	○	☐	☐

	Material	From	To	Amt	sacks/lbs
Seal:	Bentonite	1	33	32	Sacks

(3) DRILL METHOD

☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Reverse Rotary ☒ Other SERVICE TRUCK

(4) PROPOSED USE

☒ Domestic ☐ Irrigation ☒ Community
☐ Industrial/ Commericial ☐ Livestock ☐ Dewatering
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION

Special Standard ☐ (Attach copy)
Depth of Completed Well 61.33 ft.

BORE HOLE

Dia	From	To
10	0	62

SEAL

Material	From	To	Amt	sacks/lbs
Granular Bentonite	0	1.5	1	S
		Calculated	1	
		Calculated		

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other PREVIOUSLY INSTALL
Backfill placed from ft. to ft. Material
Filter pack from 33 ft. to 62 ft. Material SAND Size 10/20
Explosives used: ☐ Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount Actual Amount

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
◉	○	6	☒	1.33	5.5	.250	◉	○	☐	☐
◉	○	5	☐	0	55.33	Sdr 26	○	◉	☒	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐
○	○		☐				○	○	☐	☐

Shoe ☐ Inside ☐ Outside ☐ Other Location of shoe(s)
Temp casing ☐ Yes Dia From + ☐ To

(7) PERFORATIONS/SCREENS

Perforations Method
Screens Type Johnson V-Wire Material Stainless Steel

Perf/ Screen	Casing/ Liner	Screen Dia	From	To	Scrn/slot width	Slot length	# of slots	Tele/ pipe size
Screen	Casing	5	56.33	61.33	.021			5

(8) WELL TESTS: Minimum testing time is 1 hour

◯ Pump ◯ Bailer ◯ Air ◯ Flowing Artesian

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)

Temperature 53 °F Lab analysis ☐ Yes By
Water quality concerns? ☐ Yes (describe below) TDS amount 106 ppm

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County CURRY Twp 32.00 S N/S Range 15.00 W E/W WM
Sec 29 SE 1/4 of the SE 1/4 Tax Lot 1200
Tax Map Number Lot
Lat ° ' " or 42.77025006 DMS or DD
Long ° ' " or -124.49673843 DMS or DD
◉ Street address of well ◯ Nearest address
42764 PORT ORFORD LOOP, PORT ORFORD

(10) STATIC WATER LEVEL

	Date	SWL(psi)	+	SWL(ft)
Existing Well / Pre-Alteration			☐	
Completed Well	1/17/2022		☐	31.5

Flowing Artesian? ☐ Dry Hole? ☐

WATER BEARING ZONES Depth water was first found 31.50

SWL Date	From	To	Est Flow	SWL(psi)	+	SWL(ft)
					☐	
					☐	
					☐	
					☐	
					☐	

(11) WELL LOG

Ground Elevation 150.00

Material	From	To
Well originally drilled 12/24/2013.	0	62
Casing was 1.5' above ground level	0	62
Since being drilled the surrounding area	0	62
was raised and a vault was installed	0	62
around well & put underground. Vault was	0	62
removed and 16" of .250 steel casing was	0	62
welded to the top of the existing 6"	0	62
protective casing to raise it to 16"	0	62
above ground level and 1 sx of casing	0	62
seal was added to existing seal to raise	0	62
it to ground level. Original casing &	0	62
seal was not altered.	0	62

Date Started 1/17/2022 Completed 1/17/2022

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number 1759 Date 1/18/2022
Signed CHRISTOPHER KERSEY (E-filed)

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1493 Date 1/18/2022
Signed JAMES MACK SR (E-filed)
Contact Info (optional) Bandon Well & Pump Co. (541) 347-7867

ORIGINAL - WATER RESOURCES DEPARTMENT

THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK Form Version:
New exempt use wells must be submitted with a map and recording fee.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

CURR 53043

1/18/2022

Map of Hole

STATE OF OREGON
WELL LOCATION MAP

This map is supplemental to the WATER SUPPLY WELL REPORT

Oregon Water Resources Department
725 Summer St NE, Salem OR 97301
(503)986-0900

LOCATION OF WELL

Latitude: 42.77025006 Datum: WGS84
Longitude: -124.49673843
Township/Range/Section/Quarter-Quarter Section:
WM32.00S15.00W29SESE
Address of Well:
42764 PORT ORFORD LOOP, PORT ORFORD

Well Label: 110222

Printed: January 18, 2022

DISCLAIMER: This map is intended to represent the approximate location the well. It is not intended to be construed as survey accurate in any manner.

Provided by well constructor