RECEIVED
NOV 20 1962
STATE ENGINEER
SALEM, OREGON

Warn 106

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

State Well No. 22/31-28

State Permit No.

(1) OWNER:
Name HARRY PON
Address BURNS OREGON

(2) LOCATION OF WELL: Owners # 20
County HARNEY Driller's well number
Center of Section 28 T. 22S R. 31E W.M.
Bearing and distance from section or subdivision corner
500 yds West of BURNS JOHN DAY HIGHWAY

(3) TYPE OF WORK (check):
New Well ☑ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☐ Municipal ☐
Irrigation ☑ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☑ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☑
12" Diam. from -1 ft. to 21' ft. Gage 1/4
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☑ No
Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from None ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☑ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal Set in Rock Clay
Depth of seal 20' ft. Was a packer used? ☐ No
Diameter of well bore to bottom of seal 20 in.
Were any loose strata cemented off? ☐ Yes ☑ No Depth
Was a drive shoe used? ☑ Yes ☐ No
Was well gravel packed? ☐ Yes ☑ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes ☑ No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 54 ft. below land surface Date 10-22-62
Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☑ Yes ☐ No If yes, by whom? DRILLER
Yield: 1100 gal./min. with 86 ft. drawdown after 8 hrs.
" " " "
" " " "
Bailer test gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water 60° Was a chemical analysis made? ☐ Yes ☑ No

(12) WELL LOG: Diameter of well below casing 11 3/4
Depth drilled 425 ft. Depth of completed well 420 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
SANDY LOAM	0	6
CLAY	6	19
ROCK BLACK HARD	19	44
CLAY	44	54
GRAVEL + SAND SOME WATER	54	58
CLAY BROWN	58	360
ROCK HARD + BLACK	360	388
ROCK Red PORUS	388	393
ROCK HARD BLACK	393	420
ROCK CREVICE Loose ROCK	420	425

Work started 10-20 19 62 Completed 10-22 19 62
Date well drilling machine moved off of well 10-22 19 62

(13) PUMP:
Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME HOLLOWAY DRILLING CO
(Person, firm or corporation) (Type or print)
Address ONTARIO ORE
Drilling Machine Operator's License No. 100
[Signed] Max Holloway (Water Well Contractor)
Contractor's License No. 16 Date 11-17, 19 62

(USE ADDITIONAL SHEETS IF NECESSARY)