

WELL I.D. # L _____

(1) LAND OWNER

Owner Well Number _____
First Name Sylvester Frank (Bud) Last Name Morris

Company _____
Address PO Box 245

City Burns State OR Zip 97720

(2) TYPE OF WELL

☒ Water Well☐ Monitoring Well☐ Piezometer

(3) CURRENT OBSERVED USE

☐ Domestic☐ Community☐ Industrial☒ Irrigation
☐ Thermal☐ Injection☐ Livestock☐ Other _____

(4) BORE HOLE CONSTRUCTION

Estimated Depth of Well 103 ft.

BORE HOLE			SEAL			
Diameter	From	To	Material	From	To	Sacks / Pounds
16"				0	25	

(5) CASING/LINER

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:		0	83.9	.25"	☒	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside☐ Outside☐ None
Final location of shoe(s) _____

(6) PERFORATIONS/SCREENS

☐ Perforations
☐ ScreensType _____ Material _____

From	To	Approx Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(7) WELL TESTS

Date _____

☐ Pump☐ Bailer☐ Air☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time

Temperature of water _____
Was a water analysis done? ☐ Yes By whom _____

(8) LOCATION OF WELL (legal description)

County Harney County Map No _____
Township 24 N / S Range 31 E / W WM Section 33
SE 1/4 of the SW 1/4 Tax Lot 4400 Lot _____
Lat ° ' " or 43.43968689314235 DMS or DD
Long ° ' " or -119.01177020863594 DMS or DD
Street Address of Well (or nearest address) Sunset Valley Rd (300' E of turn)
2220 ft E. fr. SW cor, sec 33

(9) STATIC WATER LEVEL

28 ft. below land surface. Date _____
Artesian pressure lb. per square inch Date _____

(10) WATER BEARING ZONES

From	To	Estimated Flow Rate	SWL

(11) LITHOLOGY

Ground Elevation _____

Material	From	To

Estimated date originally constructed 5/15/1975

SOURCE OF DATA / INFO

☐ USGS☐ On-Site Observation
☐ Interview☒ Other Application file G-7063.
Well existed when Mr. Morris purchased the property. They had work done on the well (letter received 1/2/1976). No log found for original or subsequent work done. Additional info from application and final proof survey notes.
Letter also indicates that the local watermaster inspected the operation.
WCC note: GPS plotted & added per loc description & per WR map tool.

COMPILED BY

Halley Barnett, Groundwater Section

DATE

6/30/2021