

RECEIVED
MAY 10 1972
STATE ENGINEER
SALMON OREGON

Silver Lake, Oregon
May 8, 1972

Mr. M^{rs}. Bartholomew
Geologist
State Engineers Office.

Mr Bartholomew,
I'm answer to your letter —

of May 4. I have completed drilling
both wells and put an eight foot
concrete aggregate around each well.

No. 1 well is 444 feet deep with
an 8 inch casing, 110 ft down to rock.

No. 2. well is 170 ft deep with
14 inch casing down to rock at 70 ft.

Because of hard drilling I found it
necessary to use an 8 inch bit

the remaining 100 feet.

I have a cap for No. 1 well
but I do not have the cap for No. 2
as yet. Nor have I put on
pressure gauges.

During to my other spring
work the well operation has been
at a standstill for the past month.

I will put the cap on No. 2
in a few days and work on my
ditches and spreaders.

If the inspector could come out
in June, I should have the work
completed and I will meet him and
show him how to get to them.

Respectfully,
Russell E. Emery