RECEIVED MAY 14 1963 STATE ENGINEER SALEM, OREGON

OBSERVATION WELL

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM 10, OREGON within 30 days from the date of well completion.

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

Lake 284

State Well No. 25/19-31 Q

G-3719 State Permit No. .....

(1) OWNER:
Name O. E. White
Address 17474 W. Whitesbridge
Kerman, Calif.

(2) LOCATION OF WELL:
County Lake Driller's well number
S ¼ NE ¼ Section 31 T. 25 R. 19E W.M.
Bearing and distance from section or subdivision corner
100 ft north & 100 ft
east of SW corner

(3) TYPE OF WORK (check):
Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☐ Municipal ☐
Irrigation ☒ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒
12" Diam. from 0 ft. to 20 ft. Gage ¼
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No
Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☒ No
Manufacturer's Name
Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal Bentonite
Depth of seal 20 ft. Was a packer used? no
Diameter of well bore to bottom of seal in.
Were any loose strata cemented off? ☐ Yes ☒ No Depth
Was a drive shoe used? ☐ Yes ☒ No
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 14 ft. below land surface Date 5/9/63
Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☒ Yes ☐ No If yes, by whom? Goeres
Yield: 2375 gal./min. with 6 ft. drawdown after 6 hrs.
" " " "
" " " "
Bailer test 14ft bounce with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water 52 Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well below casing 12
Depth drilled 225 ft. Depth of completed well 225 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
top soil, sand & clay	0	18
blue clay, hard	18	20
blue clay & brown clay	20	72
lava rock, tight	72	120
lava, pourous	120	190
tight lava	190	210
pourous lava	210	222
water gravel, hard	222	225

Work started Mar 26 1963. Completed May 9 1963
Date well drilling machine moved off of well May 10 1963

(13) PUMP:
Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Gordon Goeres
(Person, firm or corporation) (Type or print)
Address Box 202, Christmas Valley R.S.
Silver Lake, Oregon
Drilling Machine Operator's License No. 136
[Signed] Gordon Goeres
(Water Well Contractor)
Contractor's License No. 305 Date May 12, 1963

(USE ADDITIONAL SHEETS IF NECESSARY)