LAKE 51642

RECEIVED
MAY 20 2005
WATER RESOURCES DEPT
SALEM, OREGON

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

LAKE 51642 WELL I.D. # L 38771
START CARD # 26 9416

(1) LAND OWNER Well Number
Name Clayton King
Address P.O. Box 7618
City Crane State Or Zip 97732

(2) TYPE OF WORK
☒ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other

(4) PROPOSED USE:
☐ Domestic ☐ Community ☐ Industrial ☒ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 205 ft.
Explosives used ☐ Yes ☒ No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
16	0	80	Bentonite			2100 LBS
				0	80	
12	80	205	—			

How was seal placed: Method ☐ A ☐ B ☒ C ☐ D ☐ E
☐ Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	12	+2	80	250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☒ None
Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
☐ Perforations Method
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
1000+	40	105	1 hr.

Temperature of water 66 Depth Artesian Flow Found
Was a water analysis done? No ☐ Yes By whom
Did any strata contain water not suitable for intended use? Too little ☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

RECEIVED
JUL 15 2005
WATER RESOURCES DEPT
SALEM, OREGON

(9) LOCATION OF WELL by legal description:
County Lake Latitude Longitude
Township 27 S N or S Range 23 E E or W. WM.
Section 19 SW 1/4 NW 1/4
Tax Lot 800 Lot Block Subdivision
Street Address of Well (or nearest address) 3 Mile N 1 Mile W off Butte Valley Rd Riley Or.

(10) STATIC WATER LEVEL:
65 ft. below land surface. Date 4-28-05
Artesian pressure lb. per square inch Date

(11) WATER BEARING ZONES:
Depth at which water was first found 103'

From	To	Estimated Flow Rate	SWL
103	201	1000+	65

(12) WELL LOG:
Ground Elevation

Material	From	To	SWL
Top Soil	0	2	—
White clay	2	21	-
Uesceular Red Brown Basalt w/ Brown Clay	21	42	
Fractured Grey Basalt	42	74	
Hard Grey Basalt	74	103	
Brown, Red, Grey, Green, White & Black Cinders (w/B)	103	201	65
Medium Brown Basalt	201	205	65

Date started 4-26-05 Completed 4-28-05

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 1521
Signed Date 4-28-05

ORIGINAL – WATER RESOURCES DEPARTMENT FIRST COPY – CONSTRUCTOR SECOND COPY – CUSTOMER