

JUN 30 1972 STATE OF OREGON

within 30 days from the date
of well completion.

(Please type or print)

STATE ENGINEER
SALEM, OREGON

LANE

State Well No. 19S/SW 13

State Permit No.

020470

WELL # 7

Address CRESWELL, OREGON

If abandonment, describe material and procedure in Item 12.

Domestic ☐ Industrial ☐ Municipal ☒
Irrigation ☐ Test Well ☐ Other ☐

....." Diam. from ft. to ft. Gage

Size of perforations	$\frac{1}{2}$	in. by	6	in.
540	perforations from	20	ft. to	50
	perforations from		ft. to	
	perforations from		ft. to	

Diam. Slot size Set from ft. to ft.

Temperature of water 50° Depth artesian flow encountered _____ ft

Gravel placed from ft. to ft.

Bearing and distance from section or subdivision corner

Artesian pressure lbs. per square inch. Date

Formation: Describe color, texture, grain size and structure of materials; and show thickness and nature of each stratum and aquifer penetrated, with at least one entry for each change of formation. *Report each change in position of Static Water Level and indicate principal water-bearing strata.*

[illegible]

Date well drilling machine moved off of well 5-31-72 19

Drilling Machine Operator's License No. 148

Contractor's License No. 126 Date 6-26-72 1972