Linn 50738

RECEIVED
NOV 25 1996
WATER RESOURCES DEPT
SALEM, OREGON

well id L09170

STATE OF OREGON WATER WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

(START CARD) # 82985

(1) OWNER: Well Number

Name Donald D Moore

Address 35296 Richardson Gap Rd

City Sebanon State Ore Zip 97355

(2) TYPE OF WORK

☐ New Well ☐ Deepening ☑ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:

☑ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger

☐ Other

(4) PROPOSED USE:

☑ Domestic ☐ Community ☐ Industrial ☐ Irrigation

☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION: 170

Special Construction approval ☐ Yes ☐ No Depth of Completed Well [redacted] ft.

Explosives used ☐ Yes ☐ No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
6	0	170				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☐ Other

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	4	0	170	160	☐	☑	☐	☐
					☐	☐	☐	☐

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

☑ Perforations Method Hand Drill

☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
100	120	1/4	70			☐	☑
120	140	1/4	72			☐	☑
140	170	1/4	80			☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
8	80	140	1 hr.

Temperature of water 59 Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata:

(9) LOCATION OF WELL by legal description:

County LINN Latitude Longitude

Township 10 S N or S Range 1 W E or W. WM.

Section 16 S W 1/4 N E 1/4

Tax Lot Lot Block Subdivision

Street Address of Well (or nearest address) 35296 Richardson Gap Rd Sebanon Ore

(10) STATIC WATER LEVEL:

80 ft. below land surface. Date Aug 30-96

Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Clean out	150	170	

Date started Aug 30 Completed Aug 30-96

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number

Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number

Signed Howard Ams Date Aug 30-96

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER