STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Westerberg Drilling, Inc.
36728 S. Kropf Rd.
Molalla, OR 97038

WELL I.D. # L 55502

START CARD # 208151

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number Reitz Well
Name City of Keizer
Address 930 Chemawa Rd NE
City Keizer State OR Zip 97303

(2) TYPE OF WORK ☐ New Well
☐ Deepening ☑ Alteration (repair/recondition) ☐ Abandonment ☐ Conversion

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☑ Cable ☐ Auger ☐ Cable Mud
☐ Other

(4) PROPOSED USE
☐ Domestic ☑ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION Special Construction: ☐ Yes ☑ No
Depth of Completed Well 403 ft.
Explosives used: ☐ Yes ☑ No Type Amount

BORE HOLE Diameter	From	To	SEAL Material	From	To	Sacks or Pounds
See	MARI	57704				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other See MARI 57704
Backfill placed from 403 ft. to 408 ft. Material Cement Grout
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	See	MARI	57704		☐	☐	☐	☐
Liner:					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None
Final location of shoe(s)

(7) PERFORATIONS/SCREENS
☐ Perforations Method See MARI 57704
☐ Screens Type Material

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☑ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
500	84		7.75 Hr.

Temperature of water 55 Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL (legal description)
County Marion
Tax Lot 2200 Lot
Township 6 S Range 3 W WM
Section 23 SW 1/4 SE 1/4
Lat ___°___'___" or ___.___ (degrees or decimal)
Long ___°___'___" or ___.___ (degrees or decimal)
Street Address of Well (or nearest address) 1065 Bair Rd.
Keizer, OR 97303

(10) STATIC WATER LEVEL
69' 4" ft. below land surface. Date 06/11/12
ft. below land surface. Date
Artesian pressure lb. per square inch Date

(11) WATER BEARING ZONES
Depth at which water was first found

From	To	Estimated Flow Rate	SWL
See MARI 57704			

(12) WELL LOG Ground Elevation

Material	From	To	SWL
We redeveloped this well and test pumped. In the process it was decided to put a cement grout plug in the bottom of the tail pipe. Well is now 403' deep.			

RECEIVED
JUN 25 2012
WATER RESOURCES DEPT
SALEM, OREGON

Date Started 05/01/2012 Completed 06/07/2012

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number 1358 Date 06/18/2012
Signed Bryan B. Stadelmann

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 688 Date 06/18/2012
Signed Steven N. Stadelmann