

Five dewatering wells installed prior to subsurface construction. No longer accessible by drill rig (below surface in narrow concrete channel. Well was cut approximately 20-25 ft below ground surface as pit was excavated. Thus discrepancy from original well depth. See Spec Std Request.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

MULT 141642

5/30/2024

Map of Hole

STATE OF OREGON WELL LOCATION MAP

This map is supplemental to the WATER SUPPLY WELL REPORT

Oregon Water Resources Department

725 Summer St NE, Salem OR 97301
(503)986-0900



LOCATION OF WELL

Latitude: 45.59836000 Datum: WGS84

Longitude: -122.71761000

Township/Range/Section/Quarter-Quarter Section:
WM1.00N1.00E5NESW

Address of Well:

5001 N COLUMBIA BLVD, PORTLAND, OR 97203

Well Label: 143220

Printed: May 29, 2024

DISCLAIMER: This map is intended to represent the approximate location the well. It is not intended to be construed as survey accurate in any manner.

Provided by well constructor

