UMAT 56510

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form.

WELL I.D. # L 44482
START CARD # 200386

(1) LAND OWNER Well Number
Name Thomas Scott or Sharon M. Tullis
Address 32293 E. Loop Rd.
City Hermiston State OR Zip 97838

(2) TYPE OF WORK
☐ New Well ☒ Deepening ☒ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 518 ft.
Explosives used ☐ Yes ☒ No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	5"	0	395	.250	☒	☐	☒	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☒ None
Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
☐ Perforations Method
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
60		518	1 hr.

Temperature of water 68° Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Umatilla Latitude Longitude
Township 4N N or S Range 29E E or W. WM.
Section 7 SE 1/4 NW 1/4
Tax Lot 200 Lot Block Subdivision
Street Address of Well (or nearest address) 32293 E. Loop Rd. Hermiston, OR 97838

(10) STATIC WATER LEVEL: Beginning Static 357 ft.
357 ft. below land surface. Date 9-3-08
Artesian pressure lb. per square inch Date

(11) WATER BEARING ZONES:
Depth at which water was first found N/A

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:
Ground Elevation

Material	From	To	SWL
Recondition procedure:			
Original start card #129891.			
Depth of well 500 ft.			
Pulled 5" liner to surface, 0 to 357.			
Cut off 6ft damaged liner.			
Added 44ft. to existing			
steel liner. 5" liner is			
now installed from 0 to 395 ft.			
Cleaned well to bottom.			
Deepened well from 500 to 518 ft.			
Perforations are now 355 to 395 ft.			
Gray basalt, hard	500	518	

RECEIVED
NOV 30 2009
WATER RESOURCES DEPT
SALEM, OREGON

Date started 8-26-08 Completed 9-3-08

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 6218
Signed Patrick Wallace Date 9-15-08

ORIGINAL – WATER RESOURCES DEPARTMENT FIRST COPY – CONSTRUCTOR SECOND COPY – CUSTOMER