

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

UMAT 57499

WELL ID. # L N/A
START CARD # 210170

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number _____
Name Power City Co-op
Address P.O. Box 444
City Umatilla State OR Zip 97882

(2) TYPE OF WORK
☐ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☒ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other _____

(4) PROPOSED USE:
☐ Domestic ☒ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☐ No Depth of Completed Well _____ ft.
Explosives used ☐ Yes ☐ No Type _____ Amount _____

HOLE			SEAL			Sacks or pounds
Diameter	From	To	Material	From	To	

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other _____

Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:							
Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐
				☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None
Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS:							
☐ Perforations		Method _____					
☐ Screens		Type _____		Material _____			
From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☐ Air ☐ Flowing
Yield gal/min Drawdown Drill stem at Time
 1 hr.

Temperature of water _____ Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did the strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata _____

(9) LOCATION OF WELL by legal description:
County Umatilla Latitude _____ Longitude _____
Township 5N N or S Range 28E E or W. WM.
Section 22 NW 1/4 NW 1/4
Tax Lot 601 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) Hwy. 395 S.
Power City Co-op, Umatilla, OR 97882

(10) STATIC WATER LEVEL:
_____ ft. below land surface. Date _____
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL

(12) WELL LOG:
Ground Elevation _____

Material	From	To	SWL
<u>Abandonment Procedure:</u>			
<u>Pumped cement, 6.5 sacks, from 397 to 195 ft.</u>			
<u>Gravel packed well from 195 to 152 ft.</u>			
<u>Pumped cement, 50 sacks, from 152 to 0.</u>			
<u>Pumped cement into 8" hole thru 2" pipe.</u>			
<u>Original well UMAT 3397, 397 ft. depth, 8" diameter</u>			
<u>Well was abandoned in accordance with State of Oregon regulations, overseen by Anderson Perry Engineering, from La Grande, OR</u>			
Date started	<u>7-12-89</u>	Completed	<u>7-13-89</u>

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
Signed _____ WWC Number _____ Date _____

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
Signed Patricia Wallace WWC Number 1218 Date 3-4-15

**WALLACE DRILLING**

1707 S.W. 18th • PENDLETON, OR 97801

PHONE (541) 276-8663

RECEIVED BY OWRD

MAR 06 2015

SALEM, OR

March 4, 2015

*Water Resources Dept.
725 Summer St. NE, Suite A
Salem, OR 97301*

Enclosed is a package of forms pertaining to the Power City Co-op well situation. They are having problems transferring the water right from the old well to the new one. The old well was abandoned by us in 1989 but no records have been found.

I have talked to Erik Thomasser, well inspector, and have been asked to submit a start card, well report, and other papers to verify the well was properly abandoned, overseen by Anderson Perry Engineering, La Grande, OR.

Hopefully this will help the Power City Co-op transfer the water rights to their new well.

Sincerely,

*Patrick Wallace
Patrick Wallace*