



5741
8490

Map of
Lundy Ditch in Sections 4 & 5
T 36 S R 14 E W.M.



T 36 S R 14 E.



Cross section Canal.

STATE ENGINEER
RECEIVED

NOV 2 1932

BALTIMORE, OREGON

I, E.B. Henry, of Klamath Falls, Ore. do hereby certify
that this map was made from notes taken during an
actual survey made by me on the 1st day of October 1932,
and that it correctly represents the works described in the
accompanying application together with the streams and other ditches
in the immediate vicinity.

E. B. Henry Surveyor.

This map made under my direction

O. T. Darley
Surveyor