



Locate well and acreage of irrigated land on plat.  
Scale: 2" = 1 Mile

STATE OF OREGON }  
County of Columbia } ss.

I, Walter Rinehart, being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

*Walter Rinehart*  
(Signature of Registrant)

Subscribed and sworn to before me this 13th day of February, 1958.

My commission expires Nov. 4, 1960

*Marie Walker Paff*  
for Oregon (Notary Public)

(SEAL)

**CERTIFICATE OF REGISTRATION**

STATE OF OREGON }  
County of Marion } ss.

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 17 day of February, 1958, at 5 o'clock A. M. and has been duly recorded in said office in Book No. 5 of Registration Statements on page 1003.

Witness my hand this 28 day of May, 1958

*Lewis A. Strubbe*  
(State Engineer)

By \_\_\_\_\_ (Deputy)