

Marion County

IN THE MATTER OF THE ISSUANCE )  
OF A CERTIFICATE OF WATER RIGHT )  
TO CORRECT AND SUPERSEDE THE )  
CERTIFICATE RECORDED ON PAGE )  
8918, VOLUME 8. )  
-----


ORDER  
AUTHORIZING ISSUANCE OF  
CORRECTION CERTIFICATE TO BE  
RECORDED ON PAGE 13315, VOL. 11.

In a letter dated May 27, 1940, Mr. James T. Chinnock made a request to this office for the correction of an error in the description of the location of the point of diversion in the certificate of water right in the name of H. J. Schneider issued November 28, 1930 and recorded on Page 8918, Volume 8 in the State Record of Water Right Certificates.

From an inspection of a copy of the application initiating the right defined by the above described certificate, and from an examination of the map which was submitted with the original application, it appears that through a clerical error in the issuance of the certificate, the location of the point of diversion was incorrectly described as being within NW $\frac{1}{4}$ NE $\frac{1}{4}$ , Section 31, Township 39 South, Range 7 West, W. M., while such point of diversion is actually located in the NW $\frac{1}{4}$ NE $\frac{1}{4}$  of Section 31, Township 39 South, Range 8 West, W. M., and a correction certificate superseding the original certificate should be issued correctly describing the location of the diversion point, and the original certificate should be cancelled.

IT IS THEREFORE HEREBY ORDERED that a correction certificate be issued and recorded on page 13315, volume 11, State Water Right Certificates, describing the point of diversion as being within the NW $\frac{1}{4}$ NE $\frac{1}{4}$ , Section 31, Township 39 South, Range 8 West, W. M., and that the original certificate, which is recorded on page 8918, volume 8, be cancelled.

Dated at Salem, Oregon, this 8th day of June, 1940.

  
CHAS. E. STRICKLIN  
State Engineer