

SECTION

S 1/2 NE 1/4

28


TOWNSHIP 28 S, RANGE 14 W, W. M.

1/4 North

1/4

S 1/2 NE 1/4

28



West

East

Map showing location of St. Sure cranberry Bogs on the S 1/2 NE 1/4 Sec 28 T. 28 R. 14 W. W. M. Coos Co. Oregon

Scale 8" to the mile
mag. var. N. 22° E.

South

APPLICATION No. 15945
PERMIT No. 11784