



**Water Right Application Map**  
 State of Oregon  
 County of Malheur

\* Shaded areas represent Ontario city limits

T 11015



Well #L100201 (Production) located 87' N and 243' E of SE  $\frac{1}{4}$  of Section 9  
 Well #L100202 (Production) located 87' N and 261' E of SE  $\frac{1}{4}$  of Section 9  
 Well #L100204 (Production) located 72' N and 371' E of SE  $\frac{1}{4}$  of Section 9  
 Well #L100207 (Injection) located 412' N and 185' E of SE  $\frac{1}{4}$  of Section 9  
 Well #L100208 (Injection) located 414' N and 305' E of SE  $\frac{1}{4}$  of Section 9  
 Well #L100209 (Injection) located 401' N and 453' E of SE  $\frac{1}{4}$  of Section 9

RECEIVED

FEB 08 2010

**TIKKER ENGINEERING**  
 A MECHANICAL CONSULTING FIRM  
 9384 W. Overland Rd. Phone: (208) 858-0218  
 Boise, ID 83709 Fax: (208) 858-0219

**Township 18 S., Range 47 E., Section 9**  
**Portion of S 1/2 of NE 1/4 of SE 1/4**

Ontario Readiness Center

DATE:	12.17.2009
DRAWN:	DR
TE JOB#	07062
SHEET SCALE:	1" = 1000'