


Township 17S Range 2W W.M.
North



Locate well and acreage of irrigated land on plat.
Scale: 2" = 1 Mile

STATE OF OREGON

County of Lane } ss.

I, Louis V. Gowdey, being first duly sworn, do hereby certify that I have read the foregoing Registration Statement and that all of the items therein contained are true to the best of my knowledge and belief.

Louis V. Gowdey
(Signature of Registrant)

Subscribed and sworn to before me this 12 day of Feb, 1958.

My commission expires NOTARY PUBLIC FOR OREGON
My Commission Expires Jan. 25, 1959 Cham
(Notary Public)

(SEAL)

CERTIFICATE OF REGISTRATION

STATE OF OREGON

County of Marion } ss.

This is to certify that the foregoing Registration Statement was received in the office of the State Engineer on the 2 day of December, 1957, at 8:00 o'clock A.M. and has been duly recorded in said office in Book No. 5 of Registration Statements on page 812.

Witness my hand this 21 day of February, 1958.
Lewis A. Stanley
(State Engineer)

By _____
(Deputy)

GR-748

March 17, 1958

L. V. Gowdey
Hayden Bridge Road
Springfield, Oregon

Dear Mr. Gowdey:

GR-748
GR-812



STATE OF OREGON
STATE ENGINEER
WATER RESOURCES DEPARTMENT
SALEM

REFER TO FILE NO. GR-748

December 3, 1957

Mr. Louis V. Gowdey
Route 1 Box 49
Springfield, Oregon

Dear Mr. Gowdey:

This will acknowledge receipt of your registration statement which we are returning to you for additional information under Items 2, 13, 14, and the plat map on the last page. We also acknowledge receipt of your check in the amount of \$15, for which our receipt No. 14048 is enclosed. We are enclosing an instruction sheet which may aid you in further completing the statement.

The well's location should be described under Item 2 by distance and bearing or by two distances and direction from the nearest government survey corner or donation land claim corner.

Item 13 should describe the pumping equipment that has been installed on the well.

Under Item 14 the location of your irrigated lands should be described showing the township, range, section, and quarter, quarter or 40 acre tract in which the irrigated acreage is located.

The plat map on the last page shows the well location referenced to the corner of the plat map, however, no section corners are described. You should check the location of the well and irrigated lands with the County Recorder's office. The plat map should reflect the information given under Items 2 and 14.

Upon receipt of the completed statement this office will issue your certificate of registration.

Very truly yours,

LEWIS A. STANLEY
State Engineer

Gwen

By Wm. S. Bartholomew
Wm. S. Bartholomew
Geologist

WSB:gw
Enc.

RECEIVED

FEB 13 1958

STATE ENGINEER
SALEM, OREGON

Springfield, Oregon.
Feb 12-1958
RFD, #1 Box 49.

Mr. Lewis A Stanley;
State Engineer.

Dear Sir: - I just recently returned from an extended trip hence my delay in returning my application for the registration of my well.

Instead of trying to correct the errors I made in my application I employed, ~~Mr. Valder~~ ~~Valder~~ a Eugene Civil engineer, to draw up new plans and am sending them to you and hope they will include all that is necessary for the registration.

Most sincerely,
Louis W. Gowdey

(Faint, mirrored text from the reverse side of the paper is visible through the page.)

December 3, 1957

Mr. Louis V. Gowdey
Route 1 Box 49
Springfield, Oregon

Dear Mr. Gowdey:

This will acknowledge receipt of your registration statement which we are returning to you for additional information under Items 2, 13, 14, and the plat map on the last page. We also acknowledge receipt of your check in the amount of \$15, for which our receipt No. 14048 is enclosed. We are enclosing an instruction sheet which may aid you in further completing the statement.

The well's location should be described under Item 2 by distance and bearing or by two distances and direction from the nearest government survey corner or donation land claim corner.

Item 13 should describe the pumping equipment that has been installed on the well.

Under Item 14 the location of your irrigated lands should be described showing the township, range, section, and quarter, quarter or 40 acre tract in which the irrigated acreage is located.

The plat map on the last page shows the well location referenced to the corner of the plat map, however, no section corners are described. You should check the location of the well and irrigated lands with the County Recorder's office. The plat map should reflect the information given under Items 2 and 14.

Upon receipt of the completed statement this office will issue your certificate of registration.

Very truly yours,

LEWIS A. STANLEY
State Engineer

By
Wm. S. Bartholomew
Geologist

WSB:gw
Enc.

Springfield, Oregon.
Nov 29 - 1957
RJD 113x 49

State Engineer:-

Dear Sir:- I remembered that I failed to inclose a check with my application regarding my well I use for irrigation. I have inclosed a check for 15.00 to cover cost of same.

Sincerely yours
Louis J. Gowdey

RECEIVED
DEC 2 1957
STATE ENGINEER
SALEM, OREGON

CR-748

June 26, 1956

Mr. Louis V. Cowdey
Route 1, Box 49
Springfield, Oregon

Dear Mr. Cowdey:

This will acknowledge receipt of your letter dated June 19, 1956 in which you request the necessary forms and instructions in connection with registering your well.

In compliance with your request, we are enclosing a well registration statement, a sheet of instructions, and a Rules and Regulations booklet.

Very truly yours,

LEWIS A. STANLEY
State Engineer

By
Wm. S. Bartholomew
Geologist

WSB:bw
Enc. 3

Springfield, Oregon.

June 19, 1956

R.F.D. #1 Box 49.

State Engineer.

Salem, Oregon

RECEIVED

JUN 21 1956

STATE ENGINEER
SALEM, OREGON

Dear Sir:- I would like information regarding the registration of wells in western Oregon.

Also blanks for registering so that I may register a well drilled before the law regarding registration was passed.

Yours Truly
Louis Gowdey.

1 Statement

1 Inst. sheet

1 Rules + Reg.