

RECEIVED

BAKE 50805

(No invoice, no charge)

STATE OF OREGON MAR 21 2001 WATER SUPPLY WELL REPORT

(as required by ORS 537.765)

WATER RESOURCES DEPT SALEM, OREGON

WELL I.D. # L 13324 START CARD # 135454

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER: James G. Aldrich, P.O. Box 255, North Boulder, OR 97867

(2) TYPE OF WORK: Alteration (repair/recondition)

(3) DRILL METHOD: Rotary Air

(4) PROPOSED USE: Irrigation

(5) BORE HOLE CONSTRUCTION: Special Construction approval No

HOLE SEAL table with columns for Diameter, From, To, Material, Sacks or pounds

How was seal placed: Method A, B, C, D, E

(6) CASING/LINER: Casing and Liner specifications table

(7) PERFORATIONS/SCREENS: Perforations and Screens table

(8) WELL TESTS: Minimum testing time is 1 hour. Yield 400+, Drill stem at 210

Temperature of water 550, Depth Artesian Flow Found

(9) LOCATION OF WELL by legal description: Baker County, 7S 38E 36 NW 1/4 NE 1/4, Tax Lot 300

(10) STATIC WATER LEVEL: 35 ft. below land surface, Date 2-19-01

(11) WATER BEARING ZONES: Depth at which water was first found

Table with columns: From, To, Estimated Flow Rate, SWL

(12) WELL LOG: Ground Elevation

Well Log table with columns: Material, From, To, SWL. Includes handwritten note: Recondition procedure: Set over well. Used 9 7/8" milling tool to drill obstruction off steel casing at 207 ft.

Date started 2-19-01, Completed 2-19-01

(unbonded) Water Well Constructor Certification: I certify that the work I performed...

(bonded) Water Well Constructor Certification: I accept responsibility for the construction...