3 1990 AUG

STATE OF OREGON WATER WELL REPORT

(as required by ORS 537.765)

WATER RESOURCES DEPT.

SALEM, OREGON

(START CARD)

(1) **OWNER:** (9) LOCATION OF WELL by legal description: Well Number:_ Name County Benton Latitude Township ______ N or S, Range__ (2) TYPE OF WORK: Street Address of Well (or nearest address) Anderson Pol New Well ☐ Deepen ☐ Recondition (3) DRILL METHOD Rotary Air Rotary Mud Cable (10) STATIC WATER LEVEL: ☐ Other 13____ ft. below land surface. (4) PROPOSED USE: Artesian pressure _ lb. per square inch. ☐ Domestic ☐ Community ☐ Industrial Irrigation (11) WATER BEARING ZONES: ☐ Thermal ☐ Injection Other Depth at which water was first found . (5) BORE HOLE CONSTRUCTION: Special Construction approval Yes Depth of Completed Well 32 Estimated Flow Rate SWL 4007 Type _ HOLE To, Material Cement (12) WELL LOG: Ground elevation Material From То SWL 0 How was seal placed: Method A B ÆC □ D □ E 9 0 16 D Backfill placed from ____ ft. to . Material 32 Gravel placed from ___ Size of gravel (6) CASING/LINER: то 32′ Gauge Steel Plastic Welded Threaded Liner: Final location of shoe(s) (7) PERFORATIONS/SCREENS: Per formator Perforations ☐ Screens Slot Tele/pipe From To Number Diameter Casing Liner П Date started. (unbonded) Water Well Constructor Certification: (8) WELL TESTS: Minimum testing time is 1 hour I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best Flowing ☐ Pump Air ☐ Bailer Artesian Yield gal/min Drawdown Drill stem at Time knowledge and belief. <u> 400+</u> 1 hr. Signed (bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment Temperature of water Depth Artesian Flow Found work performed on this well during the construction dates reported above. all Was a water analysis done? Yes By whom work performed during this time is in compliance with Oregon well Did any strata contain water not suitable for intended use?

Too little construction standards. This report is true to the best of my knowledge and belief. ☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other Depth of strata: