

108061

207652

CLACKAMAS 14723

6/9/2013

Water Quality Concerns

Material	From	To	Amt	sacks/lbs
----------	------	----	-----	-----------

(10) STATIC WATER LEVEL

[illegible]

From	To	Material	Size
------	----	----------	------

(11) WELL LOG

Casing Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
--------------	-----	---	------	----	-------	-----	-------	-----	------

[illegible]

RECEIVED BY OWRD

JUN 27 2013

SALEM, OR

Perf/	Casing/	Screen			Scrn/slot	Slot	# of	Tele/
Screen	Liner	Dia	From	To	width	length	slots	pipe size

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
---------------	----------	-----------------------	---------------

Comments/Remarks

Removed 4 inch PVC liner. Well casing and surface seal were not altered. All casing, seal and geology information above 200 ft. obtained from original logs. Static water level remained stable during deepening.