

RECEIVED

JUN 19 1998

STATE OF OREGON WATER SUPPLY WELL REPORT WATER RESOURCES DEPT. SALEM, OREGON

Cull 41-13-9 50324 WELL I.D. # L 18629 START CARD # 111569

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number 559 Name Itzen Bulb Farm Inc. Address PO Box 1124 City Brookings State OR Zip 97745

(2) TYPE OF WORK: [ ] New Well [ ] Deepening [X] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD: [X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Other

(4) PROPOSED USE: [ ] Domestic [ ] Community [ ] Industrial [X] Irrigation [ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [ ] Yes [X] No Depth of Completed Well 6'8" ft. Explosives used [ ] Yes [X] No Type Amount

Table with columns: HOLE, SEAL, Diameter, From, To, Material, From, To, Sacks or pounds. Entry: 10" 0 6'8" Not Disturbed Previously installed

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E [ ] Other N/A

Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Entry: Casing 10" +1 60 1.25 [X] [ ] [X] [ ]

Final location of shoe(s)

(7) PERFORATIONS/SCREENS: [X] Perforations Method Torch? [ ] Screens Type Slot Material Steel. From 31 To ? Slot size ? Number Diameter 10" Pipe Coating [X] [ ]

(8) WELL TESTS: Minimum testing time is 1 hour. [X] Pump [ ] Bailer [ ] Air [ ] Flowing Artesian. Yield gal/min 45 Drawdown 30'5" Drill stem at 58' Time 1 hr.

Temperature of water 52° Depth Artesian Flow Found Was a water analysis done? [ ] Yes By whom Did any strata contain water not suitable for intended use? [ ] Too little [ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other Depth of strata:

(9) LOCATION OF WELL by legal description: County Curry Latitude Longitude Township 41 N of S Range 13 E or W.W.M. Section 9 SW 1/4 SE 1/4 Tax Lot 1100 Lot Block Subdivision Street Address of Well (or nearest address) Pedrioli Drive (Clendennon well) Brookings OR

(10) STATIC WATER LEVEL: 24' ft. below land surface. Date 6/11/98 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 24'

Table with columns: From, To, Estimated Flow Rate, SWL. Entry: 24 7 45 24'

(12) WELL LOG: Ground Elevation H-300'

Table with columns: Material, From, To, SWL. Entry: 10' well silted in to 38'8" Cleaned out hole to 6'8" Surge and Developed with air and water. Pump tested added 1' of 10" casing to top of well

Date started 6/11/98 Completed 6/11/98 (unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Brandon Well + Septic Co. WWC Number (bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Jim Mack Sr. M GWC WWC Number 1493 Date 6/12/98