UPOR! . --

CURR 50609

FEB - 2 2000

STATE OF OREGON WATER SUPPLY WELL REPORT

WATER RESOURCES DEPT. SALEM, OREGON (as required by ORS 537.765) Instructions for completing this report are on the last page of this form. (9) LOCATION OF WELL by legal description: Longitude 5 EorfW. 1/4 Block Subdivision Tax Lot <u>901</u> TYPE OF WORK 32 HAKWA Street Address of Well (or nearest address) New Well Deepening Alteration (repair/recondition) Abandonment (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Air Rotary Mud Cable Date ft. below land surface. Other lb. per square inch. (4) PROPOSED USE: Artesian pressure (11) WATER BEARING ZONES: Community Industrial Domestic Thermal ☐ Injection Livestock Other (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes X No Depth of Completed Well 48 ft. SWL Estimated Flow Rate From To Explosives used Yes No Type Amount 91 1-100 SEAL HOLE Sacks or pounds Bantonite 0 (12) WELL LOG: □B □C 50/face Ground Elevation How was seal plageod: Method Other _ Material SWL Material Backfill placed from ft. Size of gravel Gravel placed from ft. to (6) CASING/LINER: To Gauge Steel Plastic Welded Threaded + Final location of shoe(s) (7) PERFORATIONS/SCREENS; Perforations Method Material Screens Tele/pipe Casing Line Diameter Completed Date started (8) WELL TESTS: Minimum testing time is 1 hour (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment ☐ Bailer Air ☐ Artesian Pump of this well is in compliance with Oregon water supply well construction standards. Drill stem at Time Yield gal/min Materials used and information reported above are true to the best of my knowledge and belief. 1 hr. (bonded) Water Well Constructor Certification: Depth Artesian Flow Found Temperature of water I accept responsibility for the construction, alteration, or abandonment work Yes By whom Was a water analysis done? performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief Salty Muddy Odor Colored Other WWC Number Depth of strata: