

New exempt use wells must be submitted with a map and recording fee.

6/9/2026

START CARD #

1082372

ORIGINAL LOG #

(2a) PRE-ALTERATION

Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
								
								
								
								

Material	From	To	Amt	sacks/lbs

(5) BORE HOLE CONSTRUCTION

BORE HOLE			SEAL			sacks/ lbs	
Dia	From	To	Material	From	To		Amt
					Calculated		
					Calculated		
					Calculated		
					Calculated		

FILTER PACK			
From	To	Material	Size

(6) CASING/LINER

[illegible]

(7) PERFORATIONS/SCREENS

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Type of Test	Yield (gal/min)	Drawdown	Drill Stem/ Pump Depth	Duration (hr)

Water Quality Concerns

From	To	Description	Amount	Units

(10) STATIC WATER LEVEL

[illegible]

(11) WELL LOG

[illegible]

Name of person(s) who assisted with construction and Trainee License # / Helper #

Assistant Name	Type	#

Comments/Remarks

The well had gone dry and is being replaced with a WHARF grant. No original well log was found. The well casing was removed using an Excavator. The bore depth was measured at 80 feet, and clear of any debris. The well was filled with "NEAT" Portland cement. Fifteen 94lb sacks of Portland cement were pumped into the bottom of the well using a Tremie pipe. Calculated amount of cement was 13.31 sks. of 94lb portland cement. Well is abandoned to OWRD standards.