KLAM 53127

WELL ID # L 38823

STATE OF OREGON WATER SUPPLY WELL REPORT (as equired by ORS 537.765)

(START CARD) # 77078

| tructions for completing this report are on the last page of this lottin | Land Control of MFI I be level description |
|--|---|
| OWNER: Well Number: 38823 | (9) LOCATION OF WELL by legal description: County Klamath Latitude Longitude |
| me Ted Story | Township 25S Nor S. Range 13E E or W. of WM. |
| D. D 0.50 | Section 29 SE 1/4 SE 1/4 |
| y Beatty State OR Zip 97621 | Tax lot 1100 Lot Block Subdivision Street Address of Well (or nearest address) 48645 Sycan Rd. Beaty, |
| TYPE OF WORK: | Street Address of Well (or nearest address) 48645 Sycan Rd. Deaty, OR 97621 |
| New Well Deepening Alteration (repair/recondition) Abandonment | (10) STATIC WATER LEVEL: |
|) DRILL METHOD: | 1 140 ft. below land surface. Date 10/19/2001. |
| Rotary Air Rotary Mud Cable Auger | Artesian pressure ib. per square inch. Date |
| Other | (11) WATER BEARING ZONES: |
|) PROPOSED USE: | Depth at which water was first found 154 |
| Domeetic Community Industrial X Irrigation | Friend Co. Peter CWI |
| Thermal Injection Livestock Other | From To Estimated Flow Rate SWL 154 248 149 |
|) BORE HOLE CONSTRUCTION: | 248 301 149 |
| ecial Construction approval Yes No Depth of Completed Well 312 ft. | 212 |
| plosives used Yes X No Type Amount | |
| HOLE SEAL Amount | (12) WELL LOG: |
| meter From To Material From To sacks or pounds Bentonite 0 19 12 Sacks | Ground elevation |
| 12 0 19 | Material From To SWL |
| 8 19 312 | brn top soil 0 1 |
| | brn clay 1 14 65 drk brn clay 14 65 |
| | drk brn clay congl 65 154 149 |
| www.seal.placed: Method A B C D E | sandy congl w/b 154 248 149 |
| Other Poured child placed from the to the Material | cinder congl w/b 248 301 149 frac gray basalt w/b 301 312 149 |
| ckfill placed from ft. to ft. Material avel placed from ft. to ft. Size of gravel | Inda And annual |
|) CASING/LINER: | |
| ner: | RECEIVED |
| nal location of shoe(s) | = IILULIVED |
| 7) PERFORATIONS/SCREENS: | DEC 1 7 2001 |
| Perforations Method | |
| Screens Type Material | WATER RESOURCES DEPT. SALEM, OREGON |
| Slot Tele/pipe From To size Number Diameter size Casing Liner | OALLIN, OREGUN |
| | |
| | Date started 10/18/2001 Completed 10/19/2001 |
| | (unbonded) Water Well Constructor Certification: |
| | I certify that the work I performed on the construction, alteration, or abandonment |
| 8) WELL TESTS: Minimum testing time is 1 hour | of this well is in compliance with Oregon water supply well construction standards. Materials used and information reports above are true to my best knowledge and |
| Pump Bailer XAir Flowing Artesian | belief. Helps |
| Trank Chame 631. | WWC Number |
| Yield gel/min Drawdown Drill stem at Time | Signed (2 12 -0) |
| 500 312 1 hr. | 1 |
| | (bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work |
| | performed on this well during the construction dates reported above. All work |
| emperature of Water 54 Depth Artesian Flow found | performed during this time is in compliance with Oregon water supply well |
| Was a water analysis done? Yes By whom | construction standards. This report is true to the best of my knowledge and ballef. WWC Mumber 1575 |
| Did any strats contain water not suitable for intended use? | Signed 0 Date/12/12/91 |
| Depth of strata: | Douglas R. Dunagan |
| AND THE RESIDENCE OF THE PROPERTY OF THE PROPE | ONSTRUCTOR SECOND COPY - CUSTOMER |

KLAM 53127

KLAMATH County Assessor's Summary Report Real Property Assessment Report

FOR ASSESSMENT YEAR 2019

May 11, 2020 8:29:59 am

Account#

295870

Map# Code - Tax # 3513-02900-01100

072-295870

Tax Status

ASSESSABLE

See Record

See Record

LEONARD HILL

Acct Status Subtype

Appraiser

Deed Reference #

Sales Date/Price

ACTIVE **NORMAL**

Legal Descr

Metes & Bounds - See legal report for full description.

Mailing Name

Agent

In Care Of

Prop Class

RMV Class

BASSO JO ANN

Mailing Address PO BOX 100

BEATTY, OR 97621

401

MA SA 11 48

NH Unit 019 63440-1

| Situs | Address(s) | Situs City |
|-------|----------------|------------|
| ID# | 48645 SYCAN RD | BEATTY |
| | | |

| Code Area | | RMV | MAV | Value Summary AV | RMV Exception CPR | | |
|-----------|---------------|-------------------|---------|---------------------|-------------------|---|--|
| 072 | Land Impr. | 32,490 258,760 | | | Land Impr. | 0 | |
| Code | Area Total | 291,250 | 129,760 | 129,760 | | 0 | |
| Gı | rand Total | 291,250 | 129,760 | 129,760 | | 0 | |

| Code Plan | | | | | Land Breakdow | n | | | |
|-----------|-----|---------|---|---------------|---------------|------|-------|------------|-----------|
| Area | ID# | RFPD Ex | | Value Source | TD% | LS | Size | Land Class | Irr Class |
| 072 | | | | CONVERTED OSD | 100 | | | | |
| 072 | 1 | | F | Market | 100 | Α | 37.88 | | |
| Ĺ | | | | | Grand T | otal | 37.88 | | |

| Code | | Yr | Stat | | Improvement Breakdown | | Total | *************************************** | Trended |
|------|-----|-------|-------|---------------|-----------------------|-----|---------|---|---------|
| Area | ID# | Built | Class | Description | | TD% | Sq. Ft. | Ex% MS Acct# | RMV |
| 072 | 6 | | 317 | GP BUILDING | | 114 | 1,656 | | 0 |
| 072 | 8 | | 354 | Corral | | 114 | 1 | | 0 |
| 072 | 1 | 1970 | 131 | RES One story | | 114 | 1,850 | | 258,760 |
| | | | | | Grand Total | | 3,507 | | 258,760 |

Comments:

ACREAGES WERE INCORRECT PER MIKE MARCUS, INCLUDED SYCAN RD 40 AC./37.88AC

OWRD STAFF NOTES: This page furnished by WRD water master office, that shows correct Township info for well location correction / verification only.