RECEIVED SEP 2 2 1997 P2857 STATE OF OREGON WATER SUPPLY WELL REPORT Instructions for completing this report are on the last page of this form. TER RESOURCES DEPT. (START CARD) # SALEM, OREGON
(9) LOCATION OF WELL by legal description: Well Number (1) OWNER: County Lane Latitude School Dist 5 - ₩ E or W. WM. N or S Range Road S/W 1/4 MAPHE Subdivision (2) TYPE OF WORK Street Address of Well (or nearest address) New Well Deepening Alteration (repair/recondition) Abandonment 30304 Old Lowene Highway. (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Air Rotary Mud Cable Auger ft. below land surface. Other lb. per square inch. (4) PROPOSED USE: Artesian pressure (11) WATER BEARING ZONES: Industrial Irrigation Domestic Community Livestock Other Thermal Injection (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes No Depth of Completed Well 300 ft. **Estimated Flow Rate** Explosives used Yes No Type _ 26 SEAL Sacks or pounds Material From (12) WELL LOG: Ground Elevation Opp - 500 Method \square A How was seal placed: Other . From To Material ft. to Material Backfill placed from 2/3 100 ft. Gravel placed from ft. to Size of gravel 2/3 (6) CASING/LINER: Plastic Welded Threaded Gauge Steel 300 Gray Sandston Casing: Liner: Final location of shoe(s) RERFORATIONS/SCREENS: Perforations Method Screens Material c/pipe Casing Liner Diamete siże From (8) WELLTESTS: Minimum testing time is 1 hour 8-19-97 Completed Date started

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number Date

SWL

SWL

53

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. WWC Number 6/3

Drill stem at

Depth Artesian Flow Found

Pump

Depth of strata:

Yield gal/min

Temperature of water ____5_2

Bailer

Was a water analysis done? 100 Yes By whom_

Salty Muddy Odor Colored Other

Did any strata contain water not suitable for intended use 200 Too little

Flowing

Time

Signed

Artesian