

New exempt use wells must be submitted with a map and recording fee.

(2a) PRE-ALTERATION

Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
4.5		0	100	Sch40				

Material	From	To	Amt	sacks/lbs
Cement	51	58	2	Sacks

(5) BORE HOLE CONSTRUCTION

BORE HOLE			SEAL			sacks/ lbs	
Dia	From	To	Material	From	To		Amt
					Calculated		
					Calculated		
					Calculated		
					Calculated		

FILTER PACK			
From	To	Material	Size

(6) CASING/LINER

[illegible]

(7) PERFORATIONS/SCREENS

[illegible]

(8) WELL TESTS: Minimum testing time is 1 hour

Type of Test	Yield (gal/min)	Drawdown	Drill Stem/ Pump Depth	Duration (hr)

Water Quality Concerns

[illegible]

(10) STATIC WATER LEVEL

[illegible]

(11) WELL LOG

[illegible]

Name of person(s) who assisted with construction and Trainee License # / Helper #

Assistant Name	Type	#
NATHAN CONNELLY	HELPER WATER	8889012

Comments/Remarks

Ran A camera down the well. Liner had parts of a broken pump wedged in the Liner at 84' Well also had foreign materials wedged in the PVC Liner. Removed PVC Liner and cleaned out well to the bottom. Developed approximately 10-15 Gallons per minute. Reinstalled New 4.5" PVC Clic lok liner in well. No other alterations were done to well.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

LINN 65215

8/10/2026

Map of Hole

STATE OF OREGON WELL LOCATION MAP

This map is supplemental to the WATER SUPPLY WELL REPORT

Oregon Water Resources Department

725 Summer St NE, Salem OR 97301
(503)986-0900



LOCATION OF WELL

Latitude: 44.47288901 Datum: WGS84

Longitude: -122.82014268

Township/Range/Section/Quarter-Quarter Section:

WM13.00S1.00W4NWNW

Address of Well:

30286 HORSESHOE LOOP
LEBANON, OR 97355

Well Label: 63030

Printed: August 10, 2026

DISCLAIMER: This map is intended to represent the approximate location the well. It is not intended to be construed as survey accurate in any manner.

Provided by well constructor

