STATE OF OREGON WATER WELL REPORT

AUG 3 1 1995

MALH 3146

WATER RESUURCES DEPT. (START CARD) # 66452 (as required by ORS 537.765) SALEM, UREGON Well Number 66452 (9) LOCATION OF WELL by legal description; (1) OWNER: Name L, G. MilleR County Malkun_Latitude_ Address 8.0. Box 1596 N or Range EDT W. WM. City WINDSOR State CA SW (2) TYPE OF WORK: Block Subdivision ☐ Abandon New Well Deepen Recondition Street Address of Well (or nearest address) (3) DRILL METHOD: (10) STATIC WATER LEVEL: ☐ Rotary Mud Cable Rotary Air Other ft. below land surface. (4) PROPOSED USE: lb. per square inch. (11) WATER BEARING ZONES: Domestic Community Industrial ☐ Irrigation ☐ Injection Other ☐ Thermal (5) BORE HOLE CONSTRUCTION Depth at which water was first found Special Construction approval Yes INO Depth of Completed Well 60 ft. Estimated Flow Rate Explosives used Yes No Type_ From SWI 60 HOLE Amount Diameter From sacks or pounds 150 (12) WELL LOG: Ground elevation How was seal placed: Method A A B Material Bentonite Backfill placed from_ Material Gravel placed from Size of gravel (6) CASING/LINER: Threaded • \Box Final location of shoe(s) (7) PERFORATIONS/SCREENS: Method TOLCH Perforations RECEIVED Screens Турс Material Tele/pipe Diameter Casing Liner 26 Vax 50 (8) WELL TESTS: Minimum testing time is 1 hour 7-/7-95 Completed . Date started Flowing ☐ Bailer ☐ Artesian (unbonded) Water Well Constructor Certification: Pump I certify that the work I performed on the construction, alteration, or abandon-Time Yield gal/min Drawdown Drill stem at ment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief. 100+ 1 hr. WWC Number Signed . Date _ (bonded) Water Well Constructor Certification: Temperature of Water ____ Depth Artesian Flow Found I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed Was a water analysis done? Yes By whom_ during this time is in compliance with Oregon well construction standards. This report Did any strata contain water not suitable for intended use?

Too little is true to the best of my knowledge and belief. WWC Number 682 Salty Muddy Odor Colored Other Depth of strata: . SECOND COPY CONSTRUCTOR THIRD COPY - CUSTOMER /