

STATE OF OREGON

ABANDONMENT WELL REPORT

(as required by ORS 537.765, OAR 690-205-0210 & OAR690-240-0395)

WELL I.D. LABEL# L

START CARD #

(1) LAND OWNER

Owner Well I.D. _____
 First Name William Last Name Gifford
 Company _____
 Address 3474 NW 6th Avenue
 City Ontario State OR Zip 97914

(2) TYPE OF WELL

water supply

ORIGINAL LOG #

(3) EXISTING CONDITIONS

(not required if well report identified in (2) describes the well's current condition)

Depth of well: 16 ft.

Filter pack from _____ ft. to _____ ft. Material _____ Size _____

Casing	Liner	Screen	Hole	Dia	Above Land	From	To	Steel	Plastic	Other Material
☒	☐	☐	☐	10		2	16	☐	☐	Aluminum
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	
☐	☐	☐	☐					☐	☐	

(4) ABANDONMENT PROCEDURE

Special Standard ☐ (Attach copy)

Casing	Liner	Screen	Hole	From	To	In-place	Pull	Perf	Size	# Perf	Other Info
☒	☐	☐	☐	8	16	☒	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			
☐	☐	☐	☐			☐	☐	☐			

Overdrill ☐ Diameter _____ From _____ To _____

(5) ABANDONMENT MATERIAL(S)

Material	Dia. (in)	From	To	Amount	sacks/ lbs	Calculated Amount
Bentonite	10	8	16	5	S	6.32

Calculate Required Amounts

If you're using Adobe, the button above will calculate required amounts based on what you enter on pp. 1-2.

Actual Cement: 0 Sacks 0 lbs. Actual Bentonite: 5 Sacks 0 lbs.
 Calculated Cement: 0 Sacks 0 lbs. Calculated Bentonite: 6.32 Sacks 0 lbs.
 Total Dissolved Solids _____ Temperature F _____

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount 5 Sacks Actual Amount 5 Sacks

(6) LOCATION OF WELL (legal description)

County MALHEUR Twp 18 S N/S Range 47 E E/W WMSec 6 SE 1/4 of the NW 1/4 Tax Lot 4000

Tax Map Number _____ Lot _____

Lat 44.033597 or _____ " DD or DMSLong -117.018146 or _____ " DD or DMS☐ Street address of well☐ Nearest address

3474 NW 6th Avenue, Ontario

(7) STATIC WATER LEVEL

Date

Above Land

SWL(ft)

SWL(psi)

Existing Well/Pre-Abandonment 09-14-202111

(8) DESCRIPTION OF ABANDONMENT

Ground Elevation _____

Removed concrete vault over the well, dug down 8 feet, cut off casing 8 feet below land surface, removed some dirt out of the casing, used compressor to blow out and clear remaining 8 feet of casing of any debris, placed 5 bags of bentonite in remaining casing, and refilled 8 foot hole with recently excavated native soil.

RECEIVED

SEPT 24 2021

OWRD

Date Started 09-14-2021 Completed 09-14-2021

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number _____ Date _____

Signed OWRD Representative

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number _____ Date _____

Signed William Gifford

Contact Info (optional) _____

WELL I.D. LABEL# L
START CARD #
ORIGINAL LOG #

(11) ABANDONMENT MATERIAL (cont.)

[illegible][illegible][illegible]

Comments/Remarks

Well inspector determined that this was a dug well, landowner and contractor abandoned in place under supervision and with the approval of the well inspector.

RECEIVED

SEPT 24 2021

OWRD