

Liner was removed from well. Hole filled with Bentonite Chips. Pipe cut off at pump house floor level and concreted flush to floor.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

MARI 72249

8/21/2026

Map of Hole

